


**Cool Designs Ltd** 

Reising the Standards in Ar Conditioning Distribution



# Pocket Handbook Of Technical Data For the **TOSHIBA** Range of Products





(SITH)ES

NEUTROL



## The equipment listed within this publication are designed for R32 Refrigerant.

R32 refrigerant is a "Mildly Flammable" refrigerant and is categories as being an A2L refrigerant.

Toshiba Indoor units designed for R32 can be coupled to suitable Toshiba R32 or R410A outdoor units, R410A indoor units CANNOT BE CONNECTED TO R32 outdoor units.

Provide mechanical protection for all installed pipe work, keep joints to a minimum, flare connections at the outdoor unit is acceptable, it is also acceptable to make the final joint at the indoor unit via a flare connection, additional joints within the building should be of a braze type connection.

When working with R32, make sure the area is well vented, if the equipment is located in a basement area, or a below ground floor "Well area", utilise additional means of ventilation.

Extract from RAV-GP range installation manual.

Since R32 is heavier than air, it tends to accumulate at the bottom (near the floor).

Ventilate properly for the working environment to prevent its combustion.

Especially in a basement or a closed room where is the high risk of the accumulation, ventilate the room with a local exhaust ventilation.

If refrigerant leakage is confirmed in the room or the place where the ventilation is insufficient, do not work until the proper ventilation is performed and the work environment is improved.

The equipment listed is designed to be installed by a qualified f-gas registered engineer.

It is strongly recommended that the installing engineer reads the installation manual provided with the equipment, before proceeding.

Extract from RAV-GP range installation manual.

 Appliance and pipe-work shall be installed, operated and stored in a room with a floor area larger than A<sub>mn</sub> m<sup>2</sup>.

How to get A<sub>min</sub> m<sup>2</sup>: A<sub>min</sub> = (M / (2.5 x 0.22759 x h<sub>0</sub>))<sup>2</sup>

M is the refrigerant charge amount in appliance in kg. h<sub>0</sub> is the installation height of the appliance in m: 0.6 m for floor standing/1.8 m for wall mounted/1.0 m for window mounted/2.2 m for ceiling mounted (For these units recommend installation height 2.5 m.).



## <u>Index</u>

Mechanical Specification RAS R32	4
Performance & Electrical Specification RAS R32 Single Splits	4
Performance & Electrical Specification RAS R32 Multi Splits	
Acoustic Data RAS Outdoor Units	5
Acoustic Data RAS Indoor Units	
RAS Multi-Split Combination Examples	6
RAS Auto Restart	7
RAS Fault codes	
Mechanical Specification RAV DI/SDI R32	
Performance & Electrical Specification RAV DI/SDI R32 Single Splits	9
Performance & Electrical Specification RAV DI/SDI R32 Multi Splits	10
Acoustic Data RAV DI/SDI Indoor Units	10
Acoustic Data RAV DI/SDI Outdoor Units	10
Replacement Technology	11
RAV DI/SDI Twin Split	12
RAV DI/SDI Triple Split	14
RAV DI/SDI Quad Split	16
RAV DI/SDI Multi Split Wiring	
Common Sensor Characteristics	
RAV###KRT Indoor Trouble Shooting	
RAV Indoor units Lamp Indication	21
Fault Codes All Commercial & VRF Systems	25
TCC-Net Central Controller Error Detection	
"Black Pear" Error Code Cross Reference	
TCC Link Local Hard-Wired Controller Guidelines	
System Configuration Menu	
TCC-Net Optional Control Accessories	
TCC-Net Control	
DI/SDI/VRF Control Configuration	
RAV DI/SDI Data Retrieval Guide	
RAV DI/SDI Network Addressing	
RAV DI/SDI Integration with AI System	
RAV DI/SDI Temperature Sensing	
Additional Publications	
Contact Details	56



## Mechanical Specifications - RAS R32 Outdoor Units

Model	Pipe	Sizes	Min/Max Pipe Sep	Max Height Separation	Pre- Charge	Add Charge	Base Charge	Dimensions (mm)	Weight (kg)
	Liquid	Suction	(m)	(+/-)	(m)	(g/m)	(kg)	. ,	( ),
	F		F	RAS Outdoor	Units	•			
RAS-05BAVG-E							0.40		21
RAS-07BAVG-E		3/8	2/15			N/A	0.40	530x660x240	21
RAS-10BAVG-E1		5/0	2/13			N/A	0.43	33070007270	23
RAS-13BAVG-E1				12			0.43		25
RAS-16BAVG-E							0.80		34
RAS-18BAVG-E		1/2	2/20			20	0.88	550X780X290	JT
RAS-24BAVG-E							1.08		
RAS-10PAVPG-E		3/8							38
RAS-13PAVPG-E			2/25	10	15	20	1.00	630x800x300	50
RAS-16PAVPG-E		1/2							
RAS-10PAVSG-E	1/4	3/8					0.51		28
RAS-13PAVSG-E		5,0					0.67	Í	
RAS-16PAVSG-E			2/2 0	12		20	0.8	550x780x290	
RAS-18PAVSG-E		1/2					1.1		34
RAS-22PAVSG-E		1/2							
RAS-24PAVSG-E			2/25	15			1.14		43
RAS-2M10U2AVG-E		2 X 3/8	2/20		20	N/A	0.85		38
RAS-2M14U2AVG-E		3/8x2	2/30	10	30		1.02	630x800x300	44
RAS-2M18U2AVG-E		5/072				N/A	_		
RAS-3M18U2AVG-E		3/8x2+ ½x1	2/50	10	50		1.05		46
RAS-3M26U2AVG-E		3/8x1+ ½x2	3/70				1.92		72
RAS-4M27U2AVG-E		3 /8X2+1/2x2	570	15	40	20	1.72	890x900x320	12
RAS-5M34U2AVG-E		3/8X3+1/2X2	3/80				2.39		78

## Performance & Electrical Specifications - RAS R32 Single Splits

Model	Capacity (kW)		Energy Rating	Phase	Power To	Soft Start	Max Current	Suggested Fuse Size	Interconnect Cable	
	Cool	Heat	Cool/Heat						Cabie	
RAS Split Systems										
RAS-05BAVG-E	1.5	2.0	A+/A+				2.40	10		
RAS-07BAVG-E	2.0	2.5	A+/A+				3.25	10		
RAS-10BAVG-E1	2.5	3.2	A+/A+				4.20	10		
RAS-13BAVG-E1	3.3	3.6	A+/A+				5.50	10		
RAS-16BAVG-E	4.6	5.4	A++/A+				7.19	16		
RAS-18BAVG-E	5.0	5.4	A++/A+				7.50	16		
RAS-24BAVG-E	6.5	7.0	A++/A+	1 Dh	,		10.55	16	3C + E	
RAS-10PAVPG-E	2.5	3.2	A+++/A+++	1Ph + N	Indoor/ Outdoor	Yes	3.40	10		
RAS-13PAVPG-E	3.5	4.0	A+++/A+++	ΤN	Outdool		4.01	10		
RAS-16PAVPG-E	4.5	4.5	A+++/A++				6.44	16		
RAS-10PAVSG-E	2.5	3.2	A++/A++				3.97	10		
RAS-13PAVSG-E	3.5	4.2	A++/A++				5.22	10		
RAS-16PAVSG-E	4.6	5.5	A++/A+				7.10	16		
RAS-18PAVSG-E	5.0	6.0	A++/A+				8.05	16		
RAS-22PAVSG-E	6.1	7.0	A++/A+				9.30	16		
RAS-24PAVSG-E	7.0	8.0	A++/A+				11.30	16		
	Amb	ient Ra	ange; Cooling	-15°C to	+46°C,	Heating	g -15°C to	+24°C		



Model	Min-Max	Capacit	ty (kW)	Energy Rating	Phase	Power	Soft	Max	Suggested			
Model	Indoors	Cool	Heat	Cool/Heat		То	Start	Current	Fuse Size	Cable		
RAS Multi Systems												
RAS-2M10U2AVG-E	2 – 2	1.0 - 3.9	1.0 – 4.9	A++/A++		Outdoor		4.17	10	3C + E		
RAS-2M14U2AVG-E	2 – 2	1.6 – 4.9	1.3 – 5.2	A++/A++			Yes	4.87	10			
RAS-2M18U2AVG-E	2 – 2	1.7 – 6.2	1.3 – 7.5	A++/A++	1Ph			6.96	16			
RAS-3M18U2AVG-E	2 – 3	2.4 – 6.5	1.9 – 8.0	A++/A++	1PII + N			8.79	16			
RAS-3M26U2AVG-E	2 – 3	4.1 – 9.0	2.0 – 11.2	A++/A++				11.67	16			
RAS-4M27U2AVG-E	2 – 4	4.2 – 9.3	2.9 - 11.7	A++/A++				13.09	20			
RAS-5M34U2AVG-E	2 – 5	3.7 – 11.0	2.7 - 14.0	A++/A+			1 [	13.64	20			
	Ar	nbient Rang	ge: Cooling	-10°C to +4	46ºC, ⊢	leating -2	20°C to	+24°C				

## Performance & Electrical Specifications - RAS R32 Multi Splits

## Acoustic Data – RAS Outdoor / Indoor Units

RAS Outdoor Units										
Model	Cool	Heat								
Model	dB(A)	dB(A)								
RAS-05BAVG-E	48	50								
RAS-07BAVG-E	48	50								
RAS-10BAVG-E1	49	51								
RAS-13BAVG-E1	50	51								
RAS-16BAVG-E1	50	52								
RAS-18BAVG-E1	50	52								
RAS-24BAVG-E1	55	55								
RAS-10PAVPG-E	46	47								
RAS-13PAVPG-E	48	50								
RAS-16PAVPG-E	49	50								
RAS-10PAVSG-E	46	47								
RAS-13PAVSG-E	48	50								
RAS-16PAVSG-E	49	52								
RAS-18PAVSG-E	49	52								
RAS-22PAVSG-E	53	52								
RAS-24PAVSG-E	53	53								
RAS-2M10U2AVG-E	45	46								
RAS-2M14U2AVG-E	45	46								
RAS-2M18U2AVG-E	47	50								
RAS-3M18U2AVG-E	47	50								
RAS-3M26U2AVG-E	47	49								
RAS-4M27U2AVG-E	47	49								
RAS-5M34U2AVG-E	51	55								
Note: Sound measured	in Pressure dB(A	)								

RAS Indoor Units									
Madal	High	Med	Low						
Model	dB(A)	dB(A)	dB(A)						
RAS-B05BKVG-E	37	-	22						
RAS-B07BKVG-E	38	-	23						
RAS-B10BKVG-E	39	-	24						
RAS-B13BKVG-E	42	-	24						
RAS-B16BKVG-E	43	-	25						
RAS-18BKVG-E	48	-	32						
RAS-24BKVG-E	48	-	35						
RAS-B10PKVSG-E	39	-	24						
RAS-B13PKVSG-E	39	-	24						
RAS-B16PKVSG-E	43	-	26						
RAS-B18PKVSG-E	44	-	31						
RAS-B22PKVSG-E	46	-	34						
RAS-B24PKVSG-E	48	-	35						
RAS-B10U2FVG-E	39	-	26						
RAS-B13U2FVG-E	40	-	27						
RAS-B18U2FVG-E	60	-	34						
RAS-B10PKVPG-E	44	-	20						
RAS-B13PKVPG-E	45	-	20						
RAS-B16PKVPG-E	46	-	22						
RAS-M10U2MUVG-E	37	-	30						
RAS-M13U2MUVG-E	38	-	30						
RAS-M16U2MUVG-E	40	-	31						
RAS-M07U2DVG-E	35	-	27						
RAS-M10U2DVG-E	35	-	27						
RAS-M13U2DVG-E	37	-	27						
RAS-M16U2DVG-E	35	-	25						
RAS-M22U2DVG-E	38	-	32						
RAS-M24U2DVG-E	39	-	33						
Note: Sound measure	ured in Press	ure dB(A)							



	RAS M	ulti-Split System	Combination Exam	nples	
			Indoor Unit Size & Duty		
Outdoor Unit	Unit 1	Unit 2	Unit 3	Unit 4	Unit 5
	05 (2.0kw)				••
	07 (2.7kw)				
	10 (4.0kw)				
RAS -2M10U2AVG -E	05 (2.0kw)	05 (2.0kw)	_		
4.0 kW	07 (2.3kw)	05 (1.7kw)	-		
-	10 (2.67kw)	05 (1.33kw)			
-	07 (2.0kw) 10 (2.39kw)	07 (2.0kw) 07 (1.61kw)	-		
-	10 (2.0kw)	10 (2.0kw)			
	05 (2.0kw)	10 (2.0KW)			
	07 (2.7kw)				
	10 (4.0kw)				
-	13 (4.4kw)				
-	05 (2.0kw)	05 (2.0kw)			
-	07 (2.7kw)	05 (2.0kw)	-		
AS -2M14U2AVG -E	10 (3.73kw)	05 (1.87kw)			
4.4 kW	13 (4.0kw)	05 (1.6kw)			
	07 (2.7kw) 10 (3.34kw)	07 (2.7kw) 07 (2.26kw)			
	13 (3.64kw)	07 (2.26kw) 07 (1.96kw)			
	10 (2.8kw)	10 (2.8kw)			
	13 (2.3kw)	10 (2.1kw)			
	13 (2.2kw)	13 (2.2kw)			
	05 (2.0KW)	10 (2.2)			
	07 (2.7KW)				
	10 (4.0KW)				
-	13 (5.0KW)				
F	16 (5.5KW)	05 (2.0)((M))			
	05 (2.0KW)	05 (2.0KW)			
-	07 (2.7KW)	05 (2.0KW) 05 (2.0KW)	-		
	10 (4.0KW) 13 (4.86KW)	05 (1.94 KW)			
-	16 (4.99KW)	05 (1.81KW)			
-	07 (2.7KW)	07 (2.7KW)			
	10 (3.94KW)	07 (2.76KW)			
	13 (4.42KW)	07 (2.95KW)			
	16 (4.73KW)	07 (2.07KW)			
	10 3.4KW)	10 (3.4KW)			
	13 (3.84KW)	10 (2.96KW)			
_	16 (4.18KW)	10 (2.62KW)			
	13 (3.4KW)	13 (3.4KW)			
S -3M18U2AVG -E	16 (3.75KW)	13 (3.05KW)	-		
6.8 kW	16 (3.4KW)	16 (3.4KW)	05 (2 01)		
	05 (2.0kw)	05 (2.0kw)	05 (2.0kw)		
	07 (2.7kw) 10 (3.4kw)	05 (2.0kw)	05 (2.0kw) 05 (1.7kw)		
	10 (3.4kw) 13 (3.78kw)	05 (1.7kw) 05 (1.51kw)	05 (1.7kw)		
	16 (3.94kw)	05 (1.43kw)	05 (1.43kw)		
	07 (2.48kw)	07 (2.48kw)	05 (1.84kw)		
	10 (3.13kw)	07 (2.11kw)	05 (1.56kw)		
	13 (3.51kw)	07 (1.89kw)	05 (1.40kw)		
	16 (3.67kw)	07 (1.80kw)	07 (1.33kw)		
	10 (2.72kw)	10 (2.72kw)	05 (1.36kw)		
	13 (3.09kw)	10 (2.47kw)	05 (1.24kw)		
	16 (3.25kw)	10 (2.37kw)	05 (1.81kw)		
	13 (2.83kw)	13 (2.83kw)	05 (1.13kw)		
	16 (2.99kw)	13 (2.72kw)	05 (1.09kw)		
	07 (2.26kw)	07 (2.27kw)	07 (2.27kw)		
	10 (2.84kw)	07 (1.98kw)	07 (1.98kw)		
	13 (3.26kw)	07 (1.76kw)	07 (1.76kw)		
	16 (3.64kw)	07 (1.59kw)	07 (1.59kw) in the heating mode. ***		

The above is an example only, for full combination tables covering up to 5 indoor units to 1 outdoor, please contact Cool Designs Technical Support.




## **RAS – Auto Restart Function**

The indoor unit is equipped with an automatic restart facility that allows the unit to restart, at the last set operating conditions, after a power failure. The operation will resume without warning three minutes after power is restored.

This feature is not set up when these systems are shipped from the factory, therefore it will need to be activated by the installing company.

Generally, the process is the same for all RAS products since approx. 2001 and is as follows:



#### To initiate auto restart:

1. Turn the power on. Green/White, On/Off light will flash.

2. Set the system to operate using the remote controller. Green/White On/Off light will be on constantly.

- 3. Press and hold down the Operation/Reset button for more than three seconds. (Less than 10 Seconds.)
- 4. The indoor unit will bleep three times to acknowledge set up. In most cases the green light changes to orange.
- 5. The system will continue to operate during this set up.
- 6. After set up the system may be stopped using the remote controller.

#### To cancel auto restart:

- 1. The system is operating. Green/White, On/Off light will be on constantly.
- 2. Stop the system operating using the remote controller. Green/White On/Off light will extinguish.
- 3. Press and hold down the operation / reset button for three seconds.
- 4. The indoor unit will bleep three times to acknowledge cancellation.
- 5. The system will have stopped operating.

This feature cannot be set if the timer is in operation.

The louver will not swing, if it was previously set, when the system auto restarts.



## Fault Codes – RAS Series

**Do Not** turn off the power supply before reading the fault codes, doing so will clear the diagnostic memory. Caution must be taken when removing the access covers as high voltages are present.

**Fault codes** are displayed through the LEDs flashing at 5 times per second. Note, the green LED will flash once per second when the system is initially powered.

More specific codes may be obtained, while in the fault mode through the wireless controller 1. Press CHK (12) to enter service mode.

- Navigate through TEMP ▲▼ buttons until all LEDs flash (From 1 to 33), accompanied by the internal buzzer – compare the displayed code with the table below.
- 3. Press CLEAR button to clear the existing fault code (controller displays 7F)





Block	distinction		Operation o	f diagnostic function				
Check Code	Block	Check code	Cause of Operation	Air Conditioner status	Display flashing error			
		0C	TA Sensor open or short circuit or indoor PCB	Operation continues				
00	Indoor PCB	0d	TC Sensor open or short circuit or indoor PCB	operation continues	Flashes when error is detected			
		11	Indoor fan motor or PCB	All OFF				
		12	Indoor PCB	Depend on cause of failure.	Depend on cause of failure.			
01	Serial signal and connecting cable	04	Indoor to outdoor communication error, (includes compressor thermostat).	Indoor unit operates, outdoor unit stops.	Flashes when error is detected.			
	14		Over current on inverter circuit, Inverter PCB or Compressor.	All OFF	Flasher often survey in			
		16	Compressor position detection error or short circuit of compressor windings.	All OFF	Flashes after error is detected 8 times.			
					17	Current detection circuit of inverter PCB error.	All OFF	
02	Outdoor PCB	18	TE or TS sensor open or short circuit or outdoor PCB.	All OFF	Flashes after error is detected 4 times.			
		19	TD sensor open or short circuit or outdoor PCB.	All OFF				
		1A Outdoor fan error or PCB		All OFF	Flashes after error is detected 8 times.			
		1b	TO sensor open or short circuit or outdoor PCB.	Operation continues.	Record error after detected 4 times but does not flash display.			
		1C	Compressor drive circuit, voltage, current, frequency abnormal.	All OFF	Flashes after error is detected 8 times.			
		07	Indoor to outdoor communication error, Indoor/outdoor PCB, interconnecting cable, compressor thermostat	Indoor unit operates, outdoor unit stop	Flash when error detected.			
03	"Others"	1d	Compressor does not rotate, lost phase, neutral, wiring.	All OFF	Flash after error is detected 8 times.			
03	including compressor	1E	Discharge temperature exceeds 117°C	All OFF	Flashes after error is detected 4 times.			
		1F	Compressor high current, power supply, compressor, Inverter PCB	All OFF	Flash after error is detected 8 times.			
		21	Return signal of outdoor unit lost, power, indoor/outdoor PCB, high temperature on TE, TC.	Indoor unit operates outdoor unit stops	Flashes when error is detected 11 times.			



## Mechanical Specifications - DI / SDI R32 Single Splits

Model	Pipe Sizes		Min/Max Pipe Sep.	Max height	Pre- Charge	Add charge	Base charge	Dimensions	Weight		
Fibuei	Liquid	Suction	(m)	separation (+/-)	(m)	(g/m)	(kg)	(mm)	(kg)		
Commercial Range											
RAV-GM301ATP-E	1/4	3/8	2/20		15		0.6		29		
RAV-GM401ATP-E	1/4	1/2	2/20	10	15	20		550X780X290	34		
RAV-GM561ATP-E		1/2	5/30	10	20		0.9		40		
RAV-GM801ATP-E			5/50		20	35			42		
RAV-GM110AATP-E											
RAV-GM1101AT8P-E	3/8	5/8	5/50		30	35	2.1	890X900X320	68		
RAV-GM1401ATP-E			5/50		50	55	2.1	09079007320	00		
RAV-GM1401AT8P-E				30							
RAV-GP561ATP-E	1/4	1/2	3/50	50	20	20	1.35	630X799X299	45		
RAV-GP801ATP-E			5/50				1.9	1050X1010X370	74		
RAV-GP1101AT-E RAV-GP1401AT-E	3/8	5/8	3/75		30	35	3.1	1550X1010X370	104		

## Performance & Electrical Specifications - DI / SDI R32 Single Splits

Model	Capacity kW		Ambient Range °C		Phase	Power To	Soft Start	Max Current	Suggested Fuse Size	Interconnect Cable	
	Cool	Heat	Cool	Heat							
Commercial Range											
RAV-GM301ATP-E	2.50	3.40						4.17	10		
RAV-GM401ATP-E	3.60	4.00			1Ph+N			5.60	10	3C + E	
RAV-GM561ATP-E	5.00	5.30						7.78	16		
RAV-GM801ATP-E	6.70	7.70	46 to -15	15 to 15				12.23			
RAV-GM1101ATP-E	9.5	11.20	40 (0 -15	15 to -15				14.20	20		
RAV-GM1101AT8P-E	9.5	11.20			3PH+N	Outdoor	Yes	4.85	10		
RAV-GM1401ATP-E	12.00	12.80			1Ph + N	Outdoor	res	20.75	32		
RAV-GM1401AT8P-E	12.00	12.80			3PH+N			7.15			
RAV-GP561ATP-E	5.30	5.60						6.55	16		
RAV-GP801ATP-E	7.10	8.00	52 to 15	15 to 27	1P+N			9.02	16		
RAV-GP1101AT-E	10.00	11.20	52 to -15	15 to -27	TL+IN			10.43			
RAV-GP1401AT-E	12.50	14.00						15.76	25		



## Electrical Specifications - DI / SDI R32 Multi Splits

Model Outdoor	Twin Indoor	Triple Indoor	Quad Indoor	Phase	Power To	Inter - Connecting Cable
		Commercial Range				
RAV-GM561ATP-E	RAV-RM301##-E	N/ A		_		
RAV-GM801ATP-E	RAV-RM401##-E	N/A	N/A	1Ph-N		
RAV-GM1101ATP-E	RAV-RM561##-E	RAV-RM301##-E	N/A			
RAV-GM1101AT(8)P-E	RAV-RM561##-E	RAV-RM301##-E		3Ph+N		
RAV-GM1401ATP-E	RAV-RM801##-E	RAV-RM401##-E	RAV-RM301##-E	1Ph-N	Outdoor	3C+E
RAV-GM1401AT(8)P-E	RAV-RM801##-E	RAV-RM401##-E	RAV-RM301##-E	3Ph+N	Outdoor	JC+E
RAV-GP561ATP-E	RAV-RM301##-E	N/ A				
RAV-GP801ATP-E	RAV-RM401##-E	N/A	N/A			
RAV-GP1101ATP-E	RAV-RM561##-E	RAV-RM301##-E	1	1Ph-N		
RAV-GP1401ATP-E	RAV-RM801##-E	RAV-RM401##-E	RAV-RM301##-E			

## Acoustic Data – DI/SDI Indoor Units

Model Indoor	High	Med	Low	Model Indoor	High	Med	Low			
Piodel Indoor	dB(A)	dB(A)	dB(A)	Model Indoor	dB(A)	dB(A)	dB(A)			
			Commerc	ial Range						
RAV-RM301KRTP-E	40	34	29	RAV-RM561BTP-E	33	29	25			
RAV-RM401KRTP-E	41	36	30	RAV-RM801BTP-E	34	30	26			
RAV-RM561KRT-E	42	39	36	RAV-RM1101BTP-E	40	36	33			
RAV-RM801KRT-E	45	41	35	RAV-RM1401BTP-E	40	36	33			
RAV-RM561UTP-E	32	29	28	RAV-RM401CTP-E	37	35	28			
RAV-RM801UTP-E	35	31	28	RAV-RM561CTP-E	37	35	28			
RAV-RM1101UTP-E	43	38	33	RAV-RM801CTP-E	41	36	29			
RAV-RM1401UTP-E	44	38	34	RAV-RM1101CTP-E	44	38	32			
RAV-RM301MUT-E	38	36	30	RAV-RM1401CTP-E	46	41	35			
RAV-RM401MUT-E	41	36	32							
RAV-RM561MUT-E	44	39	35							
RAV-RM301SDT-E	39	36	33	Note; Measu	red in Pressu	ire Db(A)				
RAV-RM401SDT-E	39	36	33							
RAV-RM561SDT-E	45	40	36							

## Acoustic Data – DI/SDI Outdoor Units.

Model Outdoor	Cooling dB(A)	Heating dB(A)	Model Outdoor	Cooling dB(A)	Heating dB(A)	Model Outdoor	Cooling dB(A)	Heating dB(A)				
	Commercial Range											
RAV-GM301ATP-E	46	47	RAV-RM401ATP-E	49	50	RAV-RM561ATP-E	46	48				
RAV-RM801ATP-E	48	52	RAV-RM1101ATP(8)-E	54	57	RAV-RM1401ATP(8)-E	54	57				
RAV-GP561ATP-E	46	48	RAV-GP801AT-E	46	48	RAV-GP1101AT-E	49	50				
RAV-GP1401AT-E 50 51												
			Note: Measured	l in Pressure D	b(A)							



## **Refrigerant Replacement Technology.**

Existing piping connection with different diameter gas and liquid line is possible using the criteria detailed below.

Toshiba Digital and Super Digital R410A and R32 outdoor units have factory fitted filters installed which enables the reuse of existing pipework.

The existing pipework **MUST** be in good condition and have a wall thickness on a minimum 1mm.

When utilising R32 equipment, any joints within the building **MUST** be braze type, the final connection to the indoor unit can be of the flare type, all pipework **MUST** be mechanically protected.

Liquid Pipe Size in "	or mm	1/4 – 6.4 (STD)				3/8 – 9.5 (1-size larger)				
Gas Pipe Size in " or	3/8 (STD)		1/2 (1-size larger)		3/8 (STD)		1/2 (1-size larger)			
Maximum Pipe Dist	Length	Pre- charged	Length	Pre- charged	Length	Pre- charged	Length	Pre- charged		
	·			m	m	m	m	m	m	
RAV-DI Series 4 – R410A Series 1 – R32	SM30*	20	15	20	15	13	7.5	13	7.5	

Liquid Pipe Size in "	or mm		1/4 - 6.4 (STD)					3/8 9.5 (1-Size larger)				
Gas Pipe Size in " or	r mm	3/8 (1-Siz	e larger)	1/2	1/2 (STD)		5/8 (1-Size larger)		1/2 (STD)		5/8 (1-Size larger)	
Maximum Distance		Length	Pre- charged	Length	Pre- charged	Length	Pre- charged	Length	Pre- charged	Length	Pre- charged	
		m	m	m	m	m	m	m	m	m	m	
RAV-DI	SM/RM40*	20	15	20	15	20	15	13	7.5	13	7.5	
Series 2 – R410A Series 1 – R32	SM/RM56*			30	20	30	20	20	10	20	10	
RAV-SDI	SP/GP40*	30	20	30	20	30	20	20	10	20	10	
Series 4 – R410A Series 1 – R32	SP/GP56*			50	20	50	20	20	10	20	10	

Liquid Pipe Size in "	or mm		1/4 (1-Siz	e smaller)				3/8	(STD)				1/2 (1-Siz	e larger)	
Gas Pipe Size in " or	mm	1/2 (1-Size	smaller)	5/8	(STD)	1/2 (1-Siz	e smaller)	5/8 (STD)		3/4 (1-Size larger)		5/8	(STD)	3/4 (1-Size larger)	
Maximum Distance		Length	Pre- charged	Length	Pre- charged	Length	Pre- charged	Length	Pre- charged	Length	Pre- charged	Length	Pre- charged	Length	Pre- charge
		m	m	m	m	m	m	m	m	m	m	m	m	m	m
RAV-DI	SM/RM80*	20	20	20	20	30	20	30	20	30	20				
Series 4 – R410A	SM/GM110*							50	30	50	30	25	15	25	15
Series 1 – R32	SM/GM140*							50	30	50	30	25	15	25	15
RAV-DI Series 3 – R410A	SM160*							50	30	50	30	25	15	25	15
RAV-SDI	SP/GP80*	30	20	30	20	50	30	50	30	50	30				
Series 4 – R410A	SP/GP110*							75	30	75	30	25	15	25	15
Series 1 – R32	SP/GP140*							75	30	75	30	25	15	25	15

Smaller pipe sizes (Performance capacity is reduced due to the effect of the gas pipe size being smaller than the standard – 1-size smaller)

Normal pipe size (STD)


Larger pipe size (1-size larger)

Not compatible



## **Digital / Super Digital Inverter Twin Splits**





#### **Pipe Specifications**

	Allo	wable Piping Lengt	h (m)	Height Diff	erence (m)	Number					
Model (RAV-)	*Total length (L+a or L+b) Maximum	Branch piping A or b to furthest indoor Maximum	<b>+</b> Subtractive pipingOutdoor to Indoora-b or b-a MaximumMaximum (+/-)		Indoor units (Δh) Maximum	Number of bent portions Maximum or less (Qty)					
GM561ATP-E	30	10	5	30	0.5	10					
GM801ATP-E	50	10	5	50	0.5	10					
GM1101ATP(8)-E											
GM1401ATP(8)-E											
GP561ATP-E	50	45	10	20	0.5	10					
GP801AT-E	50	15	10	30	0.5	10					
GP1101AT-E											
GP1401AT-E											
	Data to be ratified by manufacturer.										

Data to be ratified by manufacturer.

**‡**Maximum subtractive distance between pipe branches. Example: -

Example 1 (RAV-GM561/801ATP-E) Installed length main pipe L to distributor=18m Installed length branch a=10m (Max. 10m) Installed length branch b=6m

Example 2 (RAV-GM561/801ATP-E)

Installed length main pipe L to distributor=28m Installed length branch a=14m (Max. 10m) Installed length branch b=2m

Example 3 (RAV-GM1101/1401/SP561/801/1101/1401AT(P)-E) Installed length main pipe L to distributor=35m Installed length branch a=12m (Max. 15m) Installed length branch b=10m

Example 4 (RAV-GM1101/1401/SP561/801/1101/1401AT(P)-E)

Installed length main pipe L to distributor=60m Installed length branch a=14m (Max. 15m) Installed length branch b=2m

Example 1 🗸	
Total pipe length L + a	18 + 10= 28m ✓
Subtractive pipe length a – b	10 - 06= 4m ✓
Example 2 🗴	
Total pipe length L + a	28 + 14= 42m ×
Subtractive pipe length a – b	14 - 2= 12m ×

Example 3 🗸	
Total pipe length L + a	35 + 12= 47m ✓
Subtractive pipe length a – b	12 - 10= 2m ✔
Example 4 🗴	
Total pipe length L + a	60 + 14= 74m 🗴
Subtractive pipe length a – b	14 - 2= 12m ×



## **Additional Charge**

		Main Pipes			Branch Pipes						
Model (RAV-)	Sizes Gas/Liquid (``)	Pre-charge Factor (m)	Add Amount (kg/m) – [ α ]	Sizes (") Gas/Liquid	Pre-charge (m) Factor	Add Amount (kg/m) – [ <mark>ß</mark> ]					
GM561ATP-E											
GM801ATP-E				1/2 - 1/4		0.020					
GM1101ATP(8)-E		22									
GM1401ATP(8)-E	F /0 2 /0		0.005	5/8 - 3/8	2	0.035					
GP561ATP-E	5/8 - 3/8	28	0.035		2						
GP801AT-E				1/2 - 1/4		0.020					
GP1101AT-E											
GP1401AT-E				5/8 - 3/8		0.035					
	Data to be ratified by manufacturer.										

Gas calculation - [Main pipe] (L-**28**) x α + [Branch Pipe] (a+b - **4**) x **B**= additional charge

Example 1


Installed length main pipe L to distributor=38m Installed length branch a=12m Installed length branch b=10m

Example 1 using	GM1101ATP-E				
Total pipe length Branch pipe length	L - <b>28</b> x <b>0</b> a + b x <mark>ß</mark>	38 12	28 10 - <b>4</b>	=10 x 0.035= =18 x 0.035=	
				Add Amount	0.98 kg

NOTES:



## **Digital / Super Digital Inverter Triple Splits**



#### **Pipe Specifications**

	Allowa	ble Piping Lengths	(m)		Height Difference (m)			
Model (RAV-)	*Total Length La + Lb La + Lc Maximum	†Branch Piping La, Lb or Lc to Furthest Indoor Maximum	≠Subtractive Piping Length Lb - La Lb - Lc Maximum	Indoo Outdoor Unit Higher Maximum	or Unit - Outdoor U Indoor Unit Higher Maximum	Indoor Unit Higher Difference (Δh)		
GM1101ATP(8)-E								
GM1401ATP(8)-E		45	10	20	20		10	
GP1101AT-E	50	15	10	30	30	0.5	10	
GP1401AT-E								

Data to be ratified by manufacturer.

 $\boldsymbol{*}_{\mathsf{Total}}$  length of pipe between furthest indoor and outdoor unit.

•

 $extsf{t}$ Maximum distance of Branch pipe from main pipe distributor to furthest indoor unit.

**\ddagger**Maximum subtractive distance between pipe branches. Example: -

#### Example 1

Installed length main pipe L to distributor=38m Installed length branch =12m Installed length branch b=10m Installed length branch c=12m

Example 2

Installed length main pipe L to distributor=40m Installed length branch a=15m Installed length branch b=4m Installed length branch c=12m

Example 1 🗸			
Total pipe length L + a	38	+ 12=	50m ✓
Subtractive pipe length a – b	12	- 10=	2m ✓
Subtractive pipe length c – b	12	- 10=	2m ✓
Example 2 🗶			
Total pipe length L + a	40	+ 15=	55m ×
Subtractive pipe length a – b	15	- 4=	11m ×
Subtractive pipe length c – b	12	- 4=	8m 🗸



#### **Additional Charge**

		Main Pipes		Branch Pipes			
Model (RAV-)	Sizes (``)	Pre-charge (m)	Add Amount	Sizes (")	Pre-charge (m)	Add Amount	
	Gas/Liquid	Factor	(kg/m) – [α]	Gas/Liquid	Factor	(g/m) – [ <mark>ß</mark> ]	
GM1101ATP(8)-E		28		1/2 - 1/4		0.020	
GM1401ATP(8)-E	5/8 – 3/8		0.035	5/8 - 3/8	6	0.035	
GP1101AT-E	5/8 - 3/8		0.055	1/2 - 1/4	0	0.020	
GP1401AT-E				5/8-3/8		0.035	

Data to be ratified by manufacturer.

Gas calculation - [Main pipe] (L-**28**) x  $\alpha$  + [Branch Pipe] (a+b+c - **6**) x **B** = additional charge

•

Example 1

Installed length main pipe L to distributor=38m Installed length branch a=12m Installed length branch b=10m Installed length branch c=12m

Example 1 above	using GM1401	ATP(8)-E		
Total pipe length	L-28 xα	38 - 28	=10 x 0.035=	0.35 +
Branch pipe length	a + b + c x 🕻	12+10+ 12- <b>6</b>	=28 x 0.035=	0.98
			Add Amount	1.33 kg


Example 1 above using GP1101AT-E		
Total pipe length L - $28 \times \alpha$ 38 - 28	=10 x 0.035=	0.35 +
Branch pipe length $a + b + c \times \beta 12 + 10 + 12 - 6$	=28 x 0.020=	0.56
	Add Amount	0.91 kg

NOTES:



## **Digital Inverter Quad Splits**

Indoor Unit A



#### **Pipe Specifications**

	Allowa	ble Piping Lengths	s (m)		Hei	ight Difference (	m)	
Model (RAV-)	*Total Length (L+b+c) or (L+b+d) or (L+a+e) or (L+a+f) Maximum	†Branch Piping c, d, e & f to Furthest Indoor Maximum	¥Branch Piping b+c b+d a+e a+f Maximum	<b>‡</b> Subtractive Branch Piping (c+b) - (d+b) (c+b) - (e+a) (c+b) - (f+a) (d+b) - (f+a) (d+b) - (f+a) (e+a) - (f+a) Maximum	Outdoor Unit- Outdoor Unit higher Maximum	Indoor Unit(H) Indoor Unit higher Maximum	Indoor unit height difference (Δh) Maximum	Number of Bent portions Maximum or Less
GM1401ATP(8)-E GP1401AT-E	50	10	15	5	30	30	0.5	10

• Data to be ratified by manufacturer.

f \*Total length of pipe between furthest indoor and outdoor unit.

 $extsf{t}$ Maximum distance of Branch pipe from main pipe distributor to furthest indoor unit.

¥ Maximum pipe distance between Branched pairs

+Maximum subtractive distance between pipe branches. Example: -

Example 1 Installed length main pipe L to distributor=20m Installed length branch b=10m Installed length branch c=5m Installed length branch d=5m Installed length branch a=10m Installed length branch e=5m Installed length branch f=5m

Example 1 🗸			
Total pipe length L + b + c	20 + 10 +5=	35m√	
Branch length b + d	10 +5=	15m√	
Branch length a + e	10 +5=	15m√	
Branch length a + f	10 +5=	15m√	
Subtractive pipe length c+b - d+b	5+10 - 5+10=	0m√	
Subtractive pipe length c+b - e+a	5+10 - 5+10=	0m√	
Subtractive pipe length c+b - f+a	5+10 - 5+10=	0m√	
Subtractive pipe length d+b - e+a	5+10 - 5+10=	0m√	
Subtractive pipe length d+b - f+a	5+10 - 5+10=	0m√	
Subtractive pipe length e+a - f+a	5+10 - 5+10=	0m√	



#### Example 2 Installed length main pipe L to distributor=30m Installed length branch b=15m Installed length branch c=10m Installed length branch d=6m Installed length branch a=15m Installed length branch e=5m Installed length branch f=10m

Example 2 ×		
Total pipe length $L + b + c$	30+ 15 + 10	= 55m×
Branch length $b + c$	15+ 10	= 25m×
Branch length b + d	15+ 6	= 21m×
Branch length a + e	15+ 5	= 20m×
Branch length a + f	15+ 10	= 25m×
Subtractive pipe length c+b - d+b	10+ 15- 6+ 15	= 4m√
Subtractive pipe length c+b - e+a	10+ 15- 5+ 15	= 5m√
Subtractive pipe length c+b - f+a	10+ 15- 10+ 15	= 0m√
Subtractive pipe length d+b - e+a	6+ 15- 5+ 15	= 1m√
Subtractive pipe length d+b - f+a	6+ 15- 10+ 15	= 1m√
Subtractive pipe length e+a - f+a	6+ 15- 10+ 15	= 1m√


#### Additional Charge

		Main Pipes			Branch pipes						
Model	Sizes Gas/Liquid (``)	Pre-charge Factor (m)	Add amount $(kg/m) - [\alpha]$	Sizes Gas/Liquid (``)	Pre-charge Factor (m)	Add amount (g/m) – [ß]	Sizes Gas/Liquid (")	Add amount (g/m) – [ <b>y</b> ]			
GM1401ATP(8)-E	5/8 – 3/8	28	0.035	3/8 - 1/4	4	0.020	1/2 – 1/4	0.020			
GP1401AT-E			0.035	3/8 - 1/4	+	0.020	1/2 - 1/4	0.020			
			• Date	a to be ratified by m	nanufacturer.						

Gas calculation - [Main pipe] (L-28) x  $\alpha$  + [Branch Pipe] (a + b - 4) x  $\beta$  + (c+d+e+f) x  $\gamma$  = additional charge

Example 1 Installed length main pipe L to distributor=20m Installed length branch b=10m	Example 1 using GM14	401ATP(8)-E			
Installed length branch c=5m Installed length branch d=5m Installed length branch a=10m Installed length branch e=5m Installed length branch f=5m	Total pipe length Branch pipe length Branch pipe length	L - 28 x α. a + b - 4 x β c + d + e + f x γ	20 - 28 10+10- <b>4</b> 5+5+5+5	=-8 x 0.035 = =16 x 0.020 = =20 x 0.020 = Add Amount	-0.28 + 0.32 + 0.40 0.44 kg

## Digital / Super Digital Multi Split System Wiring Schematic





#### Common Sensor Characteristics

There are eight commonly used sensors in the **RAS** and **RAV** systems.

- TA = Return Air Sensor; indoor unit
- TL = Liquid Pipe Sensor (fan speed); outdoor unit
- TD = Discharge Pipe Sensor; outdoor unit
- TS = Suction; outdoor unit


- TC = Coil Sensor; indoor unit
- TCJ = Coil Sensor; indoor unit
- TE = Heat Exchange Sensor (defrost); outdoor unit
- TO = Ambient; outdoor unit
- TK = Oil sensor (VRF)

The Ta,Tc,Tcj,Ts,To and TE sensors all share the same resistance versus temperature characteristic. They differ however in electrical connections and sensing head style; therefore, it is important to quote the full model type number when ordering any replacement sensors.


The Td, TL and TK sensor has a different resistance characteristic because its sensing range is that much higher than the others.

Sensor	-10	-5	0	5	10	15	20	25	30	35	40	45	50	55	60	100	٥C
Ta,Tc,Tcj,TE,To, Ts	60.3	45.3	33.8	26.4	20.35	16	12.59	10	8	6.5	5.2	4.3	3.5	2.9	2.4	-	KΩ
Td, Tk, TL	-	-	161	-	99	80.5	63	50	40	-	26.5	-	17.9	-	12.3	3.4	kΩ

## Example for location of sensors









## Indoor Lamp Indication for Trouble Shooting - RAV ###KRT (High wall Only)

· Constal, Ca. Constant - Ca. Flands (21.5 mill.)

Larp (Idealor)	Check code	Cause of tro-	ubel (scomerce					
	~	Name' stapping CPT of minimizing better	mention and and justice and					
	1011	tokaring entri (						
	600	Sinding mile	Noticements or with communities enter perturbation recenting white and indexed or					
	693	Contrainulusi mgi						
finally, fine communi-	100	Dugik and moor unit fin						
• • ×	2.00	Chiphand maine with at twenty tallander						
YEAN	T IN	Companyation and feelings (243) or recorded TC loant						
	2.00		With convectory error between known calls, index power CPT Community large temperatures show market and balance or temperatures and tab factor have					
	158	Research Communication (1990) and and and communication (1990) behavior indexe						
roady toor operation	PGI	Patory ASTen while						
	Http://	CVING WHI DRICHT /PRODUCT	entry and a monor sent working -					
Additional Acta	ittiz	indoor DC tan ettin						
	PEI	Ourses unit discharge temp anno.						
		Outbor regripersulty system ander Calor Inventional Moderal	Photoschult teleficie of est					
	68	Prawly statistic statist						
	201	Prosent suggety certa	1					
Binady's Direct's Operations	9433	I hiar and wentious once	CORDOX and array					
. 0 0	31111	Carland (105300 (105						
A 🔹 A	P114	E-way laten ligtami ettar (babaac et a	NUMBER OF THE PARTY OF THE PART					
Alternation Restly	100	Okliber 446 Bigs (Hersale protocol)	1.					
	972	Chalabor unit: Chalabor set 8 bitte	1					
	- F96	Cublon and married tip specifies	Distriction deutice of 41 0.0000 anti-watering 41					
	(123)	Outpor unit (Rodan direction inter						
	¥01	Tabaptent because of streat of lattice and (Division contine of EditArchitecturing)	Погият = е днир					
Examp indecalling	Check cook	Cause of the	abe boxaneeus					
Singly here condition		Charteng time( tur)						
CG <sup>R</sup>	=	Chargement of Acceleration (Australia concerned weight to salarity satisfy or realising to coaling only real						

1,mp Hilliation	Check code	Cause of trial	Elle occurrence				
and the diam	707	Hait includer server (TCI) mo					
•	F02	Head iombianger semicir/TCF intoc	Bridock state premior setter				
Ahimanitian	7.59	Hold exchanges summar (18) errors					
	TOF	Discharge temp service (TQ) ince:	1				
	400-	Temps sensor (FL: To, TE) work					
Booty Trees Operation	£07	Tempi semur (TD) (mor					
0 0 0	100	Simp sense (10) mm	Searces datter et -1				
Allettine flash	712	Simplecture (15) error					
	- FG	Hear slik somer (755 ymar					
	8.52	Server second creasing (TE, 752					
Leady Inter Openant	129	Induce TEPOCM second					
Ready Error Oceanitor	9 <b>39</b> )	Outduor EEP9004 error					
Ready Tener (Decusion)	1471	Depression 1 or	tász compresar cystem erroz =+1.				
5 O O	HE	Compares tox	and and and the second of the				
• di •	(402)	Convert doministratives ) Pla	ere happy ration PC board error				
Comit	ini.	Cast themouse worked     Co	represent confisie, sutther silling res				
	100	Duplicatory mesant indoor units					
Bendy Times Openation	1.007	There is indoor unit of group corevection is shiftedual industriant.	- AlTID address • If going conduction and address				
원 후 쭈	100	Desetting of group address	we not rearral when posine supply termed in, automatically goins to				
Smullaneous Rank	1,09	Minued setting Elimet enhor capitally?	address simp mode.				
	1.60	Linest midd (yw (Service )meet)					
Ready Tarue Operation	1.00	Digitation with an around addresses					
Stutionen fait	129	Timp: server (TM) empr EEPPCM ents Communication between outdoor MCS Heat sold other time rents Cars sold, detection rents A using soles amore					

The primary judgement to check whether a fault has occurred in the indoor or outdoor unit is carried out with the following method; method to judge the erroneous position by flashing indication on the display part of the indoor unit. The indoor unit monitors the operating status of the air conditioner and the blocked contents of self diagnosis are displayed restricted to the above cases if a protective circuit works.



#### Check Code List (Indoor)

#### (Indoor unit detected)

🔾 : Go on, 🔿 - Flush, 🖕 : Go off 🐘 AET (Alternate flashing sites mere are two tashing LED - SIM (Similarinous): Similarinous): Similarinous)

Check code indication	5m	ricar liant	e initiaat	tian			Aircondition	Mer operation
Wired remote controller		Diack In	dication	Fireford	Representative defective position	Explanation of error contents.	Automatic	Operation
£03	•		0		Program communications once between indicer and communicativelier.	No commute attent from tomote controller and lettwork adaptive Which on commute attent from control portion system.	O	×
. E.Ø.4	0				Matocia Canding: 4,004 (1979)	There is entry or sental partners duallos between instance and cutdoor wills.	0	×
1.08	•		0		Originated ladian addresses	Sami addmis as yours and didected.	O:	×
6.T.B			٥.		Requiring concentration areas before an a	Require conversion-store burn between whom manuer and follower units is experiently, Communication furneeen term machine training and Saleseen Fault and a site of bringer the	0	×
01	•	0	0	TAD	Hatoor iant, Hoot enclanger (10.2) strok	Oper/sheet was detected on field exiting of (TCJ).	Q	×
8.92		e	0	A\$7	Indices and, Heart exchanger (\$12) serve	Open/Wenthers presented on laser exchanger (112)	0	×
FOOD.	0	0	0	'ALL	Refool UNIC Room withly sentuck (194) enter	Open/Shiet was detented on rocer littlig. Service (IA)	0	×
124	•	G	0	5IM .	Brook and littles would PE' bothit mint	EEPROM style (Other arrowing be detected. 9 millions, admittals, address in registration	×	×
E.03	0		0	2100	Duplicated setting of indoor group matter unit	There are maltiple moure and, ar group	×	×
102	0		6	SM	There is group callet in milestal veloci and	When parts wer group connection accord and exists in automatical autors and	× .	×
1.00	0	•	0	SIM	Orner Indoor (jmoj) addresa 🔶	hidden (m) is attracts a smart	8	×
1.09	0	•	6	SIN	Almust autoos myumity	Cognetity of waters unit in land.		×
1.20	( @)	0	(B)	SMA	Orgilicated control control system address	Duplicated saturg of control control system address	0	×
1,100	0	0	8.	504	Outputs later sports presses and theinitized	Abnormal stop by buildle setter (Chatro) import	×	×
1912	Ø.		•	747	Indoor unit, QC tan orne	Indoor DC fan enw IChver Garren/Cock, stcd wijs ergikted.	×	×
P19	0	0	2	ALL	4-way suber system care	to nearling operation, on error was detected by tamp, down of induor host antibility sense.	0	×
P31	0		6	TIA	Other autoor and orbit.	Follower unit in group cannot operate by warning from (FOR) 010.077,000 of municy and	0	×

When this warring was detected before group constrainten/address check firesh at power supply was turned on, the mode shifts automatically to ALTO address setting mater.

#### (Remote controller detected)

Chock code indication	Se	etor In	mp indica				Air conditioner opera	
Wired Immole controller Black indication	indication	<u> </u>	Representative detective position	Explanation of irror comunity	Automatic	Operation		
			0,6914	esatigeneting				
TOT	•		9		No mester remain controllor. Remain committee communication (Recorder etra)	Signal convex to received turis indoor will. Metal remote controller was out set unduding 2 controlle controllers		
102	•	ø	100		Runpolie currendur oprimitarication (Sond) anter	Signal consent for selfit to index unit.		
EOP			9		Oughcannil manual roomat roomatha	(iv.2 compose controllor compol, both series setties manter (notice matter and steps warning and subswer only controller operation.)	×	

#### (Central control devices detected)

Chock code mdication	Sensor limp indication			Air condition	ser operation
TCC-LINK central	Block Indication Realty Time Operating Fleeh	Representative defactive position	Explanation of error contents	Automatic reside	Operation
1005	To trai strapportal	Contral accurst systems communication owned write	Separt senders operation of control control system is legaristic. There are maltiple sume control devices, 1/0/NLT1	71	
100fii	mananchici vicelatective: entr. 3	Control control sympty communication (receive) inter-	Signal recoving apartmics of contrar cannot system as improvable.		
612	-	General parpmenteers cannol surface barried warrent	An error of device presented to greened pagets, device contra introduce of exclusive to TCC-CINKIN-MET		
Pciti	Start generative VIT	Ginija simierie cist tristmieten.	Cracip influence points definitive: of or remote controller, above examinment (+++) remain any simpleyers with ram him	-	-

NOTE: Even for the same contents of error sich as communication error, the display of check code may diffur according to detection device. When remote controller or control communic districts an error, it is not recursively related to operation of the air conditioner. In this list, the check codes that wildow unit desicts we not described



## Indoor Lamp Indication for Trouble Shooting - RAV Series

● : Go off, 〇 : Go on, 米 : Flash (0.5 sec.)

Lamp indica	ation	Check code	Cause of trouble occurrence			
Operation Timer  No indication	Ready ● n at all	_	Power supply OFF or miswiring between receiving unit and indoor unit			
		E01	Receiving error Receiving unit			
		E02	Sending error Sending error Sending error Sending error			
0 ° T	5	E03	Communication stop			
Operation Timer	Ready	E08	Duplicated indoor unit No.			
+ ★ ● Flash	•	E09	Duplicated master units of remote controller			
1 10511		E10	Communication error between CPUs on indoor unit P.C. board			
		E18	Wire connection error between indoor units, Indoor power OFF (Communication stop between indoor master and follower or between main and sub indoor twin)			
Operation Timer	Ready					
• •	$\ast$	E04	Miswiring between indoor unit and outdoor unit or connection erorr (Communication stop between indoor and outdoor units)			
	Flash					
Operation Timer	Ready ★	P10	Overflow was detected.			
L Alterr	nate flash	P12	Indoor DC fan error			
		P03	Outdoor unit discharge temp. error Protective device of *1			
		P04	Outdoor high pressure system error outdoor unit worked.			
		P05	Negative phase detection error			
		P07	Heat sink overheat error Outdoor unit error			
Operation Timer	Ready	P15	Gas leak detection error			
* •	*	P19	4-way valve system error (Indoor or outdoor unit judged.)			
Alternate fl	lash	P20	Outdoor unit high pressure protection			
		P22	Outdoor unit: Outdoor unit error			
		P26	Outdoor unit: Inverter Idc operation Outdoor unit worked.			
		P29	Outdoor unit: Position detection error			
		P31	Stopped because of error of other indoor unit in a group (Check codes of E03/L03/L07/L08)			
Operation Timer -껒껒- Simultaneou	Ready -ໍ္လຸ່- s flash	_	During test run			
Operation Timer O -Ờ- Ĺ Alterr	Ready -Ò- nate flash	_	Disagreement of cool/heat (Automatic cool/heat setting to automatic cool/heat prohibited model, or setting of heating to cooling-only model)			

Lamp indication	Check code	Cause of trouble occurrence				
Operation Timer Ready	F01	Heat exchanger sensor (TCJ) error				
-☆☆- ●	F02	Heat exchanger sensor (TC) error	Indoor unit sensor error			
Alternate flash	P10	Heat exchanger sensor (TA) error				
	F04					
	F06	Discharge temp. sensor (TD) error				
Operation Timer Ready	F07	Temp. sensor (TE) error Temp. sensor (TL) error				
	F08	Temp. sensor (TO) error	Sensor error of outdoor unit *1			
Alternate flash	F12	Temp. sensor (TS) error Temp. sensor (TH) error				
	F13	Temp. Sensor miswiring (TE, TS)				
	F15					
Operation Timer Ready -☆☆- ● LL Simultaneous flash	F29	Indoor EEPROM error				
Operation Timer Ready -☆☆- O ii Simultaneous flash	F31	Outdoor EEPROM error				
	H01	Compressor break down Compressor lock Current detection circuit error Outdoor compressor system e Case thermostat worked. Outdoor unit low pressure system error				
Operation Timer Ready	H02					
● <u>-ờ</u> - ●	H03		oor compressor system error *1			
Flash	H04					
	H06	Culdon unit low pressure system entri				
	L03	Duplicated master indoor units				
Operation Timer Ready -☆- ● -☆-	L07	There is indoor unit of group connection in individual indoor unit. Unsetting of group address	→ AUTO address * If group construction and			
Simultaneous flash	L08	Missed setting (Unset indoor capacity)	address are not normal when power supply turned on, automatically goes to address			
	L09	· · · · · · · · · · · · · · · · · · ·	setup mode.			
	L10					
Operation Timer Ready	L20	Unset model type (Service board) Duplicated indoor central addresses				
× o ×	L29	Outdoor unit and other error	Others			
Simultaneous flash	L30	Outside interlock error Negative phase error				
	L31					

The primary judgment to check whether a fault has occurred in the indoor unit or outdoor unit is carried out with the following method; method to judge the erroneous position by flashing indication on the display part of the indoor unit. The indoor unit monitors the operating status of the air conditioner and the blocked contents of self-diagnosis are displayed restricted to the above cases if a protective circuit works.



#### Check Code List (Indoor)

○ : Go on, 🍥 : Flash, ● : Go off ALT (Alternate): Alternate flashing when there are two flashing LED SIM (Simultaneous): Simultaneous flashing when there are two flashing LED

#### (Indoor unit detected)

Check code indication Indoor Sensor lamp indication					ner operation			
TCC-LINK central & Wired remote controller		Block in			Representative defective position	Explanation of error contents	Automatic	Operation continuation
whed remote controller	Operatio	n Timer	Ready	Flash			Teset	continuation
E03	0	۲	•		Regular communication error between indoor and remote controller	No communication from remote controller and network adapter (Also no communication from central control system)	0	×
E04	۲		0		Indoor/Outdoor serial error	There is error on serial communication between indoor and outdoor units	0	×
E08	0	•	•		Duplicated indoor addresses 🔶	Same address as yours was detected.	0	×
E10	0	•	•		Communication error between indoor MCU	MCU communication error between main motor and micro computer	0	×
E18	0	٠	۲		Regular communication error between indoor master and follower units	Regular communication between indoor master and follower units is impossible, Communication between twin master (main) and follower (sub) units is impossible.	0	×
F01	0	0	۲	ALT	Indoor unit, Heat exchanger (TCJ) error	Open/short was detected on heat exchanger (TCJ).	0	×
F02	0	0		ALT	Indoor unit, Heat exchanger (TC) error	Open/short was detected on heat exchanger (TC).	0	×
F10	0	0	۲	ALT	Indoor unit, Room temp. sensor (TA) error	Open/short was detected on room temp. sensor (TA).	0	×
F29	0	0	۲	SIM	Indoor unit, other indoor P.C. board error	EEPROM error (Other error may be detected. If no error, automatic address is repeated.	×	×
L03	0		0	SIM	Duplicated setting of indoor group master unit $~~~~~~~~~~~~~~~~~~~~~~~~~~~~~~~~~~~~$	There are multiple master units in a group.	×	×
L07	0	•	0	SIM	There is group cable in individual indoor unit. $\diamond$	When even one group connection indoor unit exists in individual indoor unit.	×	×
L08	0	•	0	SIM	Unset indoor group address 🛛 🔶	Indoor group address is unset.	×	×
L09	0	•	0	SIM	Unset indoor capacity	Capacity of indoor unit is unset.	×	×
L20	0	0	0	SIM	Duplicated central control system address	Duplicated setting of central control system address	0	×
L30	0	0	0	SIM	Outside error input to indoor unit (Interlock)	Abnormal stop by outside error (CN80) input	×	×
P01	•	0	0	ALT	Indoor unit, AC fan error	An error of indoor AC fan was detected. (Fan motor thermal relay worked.)	×	×
P10		0	0	ALT	Indoor unit, overflow detection	Float switch worked.	×	×
P12		0	0	ALT	Indoor unit, DC fan error	Indoor DC fan error (Over-current/Lock, etc.) was detected.	×	×
P19	0	۲	0	ALT	4-way valve system error	In heating operation, an error was detected by temp. down of indoor heat exchanger sensor.	0	×
P31	0	•	0	ALT	Other indoor unit error	Follower unit in group cannot operate by warning from [E03/L03/L07/L08] of master unit.	0	×

When this warning was detected before group construction/address check finish at power supply was turned on, the mode shifts automatically to AUTO address setup mode.

#### (Remote controller detected)

Check code indication Indoor Sensor		door Sensor lamp indication					Air condition	ner operation
Wired remote controller	Block indication				Representative defective position	Explanation of error contents	Automatic	
wired remote controller	Operatio	Operation Timer Ready Flash		Flash			reset	continuation
E01	0	٠	٠		No master remote controller, Remote controller communication (Receive) error	Signal cannot be received from indoor unit. Master remote controller was not set. (including 2 remote controllers)	-	-
E02	0	•	•		Remote controller communication (Send) error	Signal cannot be sent to indoor unit.	_	—
E09	0	٠	٠		Duplicated master remote controller	In 2-remote controller control, both were set as master. (Indoor master unit stops warning and follower unit continues operation.)	×	Δ

#### (Central control devices detected)

Check code indication	Indoor Sensor lamp indication			Air condition	ner operation
TCC-LINK central	Block indication	Representative defective position	Explanation of error contents	Automatic	Operation continuation
ICC-LINK Central	Operation Timer Ready Flash				continuation
C05	(Common use of	Central control system communication (send) error	Signal sending operation of central control system is impossible. There are multiple same central devices. (AI-NET)	-	-
C06	remote controller, etc.)	Central control system communication (receive) error	Signal receiving operation of central control system is impossible.		_
C12	-	General-purpose device control interface batched warning	An error on device connected to general-purpose device control interface of exclusive to TCC-LINK/AI-NET	-	—
P30	By warning unit (Above-mentioned)	Group follower unit is defective.	Group follower unit is defective. (For remote controller, above-mentioned [***] details are displayed with unit No.	-	_

NOTE: Even for the same contents of error such as communication error, the display of check code may differ according to detection device. When remote controller or central controller detects an error, it is not necessarily related to operation of the air conditioner. In this list, the check codes that outdoor unit detects are not described.



## Indoor Lamp Indication for Trouble Shooting - RAV Series

#### Check Code List (Outdoor)

O : Go on, ⊚ : Flash, ● : Go off ALT (Alternate): Alternate flashing when there are two flashing LED SIM (Simultaneous): Simultaneous flashing when there are two flashing LED

Remote	Ind	oor Sens	or lamp	part				Automotio	Operation
controller		Block in			Representative defective position	Detection	Explanation of error contents	Automatic reset	Operation continuation
	1	n Timer	Ready	Flash		-			
F04	0	0	0	ALT	Outdoor unit Discharge temp. sensor (TD) error	Outdoor	Open/Short of discharge temp. sensor was detected.	×	×
F06	0	0	0	ALT	Outdoor unit Temp. sensor (TE, TS, TL) error	Outdoor	Open/Short of heat exchanger temp. sensor was detected. Miswiring between TE sensor and TS sensor	×	×
F08	0	0	0	ALT	Outdoor unit Outside temp. sensor (TO) error	Outdoor	Open/Short of outside temp. sensor was detected.	0	0
F07	0	0	0	ALT	Outdoor unit Temp. sensor (TL) error	Outdoor	Open/Short of heat exchanger temp. sensor was detected.	×	×
F12	0	0	0	ALT	Outdoor unit Temp. sensor (TS) error	Outdoor	Open/Short of suction temp. sensor was detected.	×	×
F13	0	0	0	ALT	Outdoor unit Temp. sensor (TH) error	Outdoor	Open/Short of heat sink temp. sensor (Board installed) was detected.	×	×
F15	0	0	0	ALT	Outdoor unit Misconnection of temp. sensor (TE, TS)	Outdoor	Misconnection of outdoor heat exchanger temp. sensor and suction temp. sensor was detected.	×	×
F31	0	0	0	SIM	Outdoor unit EEPROM error	Outdoor	Outdoor P.C. board part (EEPROM) error was detected.	×	×
H01	•	0	۲		Outdoor unit Compressor break down	Outdoor	When reached min-Hz by current release control, short-circuited current (Idc) after DC excitation was detected.	×	×
H02	•	0	•		Outdoor unit Compressor lock	Outdoor	Compressor lock was detected.	×	×
H03	•	0			Outdoor unit Current detection circuit error	Outdoor	Current detection circuit error	×	×
H04	•	0	•		Outdoor unit Case thermostat operation	Outdoor	Case thermostat operation was detected.	×	×
L10	0	0	0	SIM	Outdoor unit Setting error of service P.C. board type	Outdoor	When outdoor service P.C. board was used, model type select jumper setting was inappropriate.	×	×
L29	0	0	0	SIM	Outdoor unit Other outdoor unit error	Outdoor	<ol> <li>Defective parts on outdoor PC. board (MCU communication, EEPROM, TH sensor error)</li> <li>When outdoor service PC. board was used, model type selection was inappropriate.</li> <li>Other error (Heat sink abnormal overheat, gas leak, 4-way valve inverse error) was detected.</li> </ol>	×	×
P03	0	•	0	ALT	Outdoor unit Discharge temp. error	Outdoor	Error was detected by discharge temp. release control.	×	×
P04	0	•	0	ALT	Outdoor unit High pressure system error, Power supply voltage error	Outdoor	When case thermostat worked, error was detected by high release control from indoor/ outdoor heat exchanger temp. sensor. Power supply voltage error	×	×
P05	0	•	0	ALT	Power supply error	Outdoor	Power supply voltage error	×	×
P07	0	۲	0	ALT	Outdoor unit Heat sink overheat	Outdoor	Abnormal overheat was detected by outdoor heat sink temp. sensor.	×	×
P15	0	•	0	ALT	Gas leak detection	Outdoor	Abnormal overheat of discharge temp. or suction temp. was detected.	×	×
P20	0	•	0	ALT	Outdoor unit High pressure system error	Outdoor	Error was detected by high release control from indoor/outdoor heat exchanger temp. sensor.	×	×
P22	0	•	0	ALT	Outdoor unit Outdoor fan error	Outdoor	Error (Over-current, lock, etc.) was detected on outdoor fan drive circuit.	×	×
P26	0	•	0	ALT	Outdoor unit Inverter Idc operation	Outdoor	Short-circuited protective operation of compressor drive circuit element (G-Tr /IGBT) worked.	×	×
P29	0	•	0	ALT	Outdoor unit Position detection error	Outdoor	Position detection error of compressor motor was detected.	×	×
E01	0	٠	٠		No remote controller master unit Remote controller communication error	Remote controller	Signal was not received from indoor unit. Main remote controller was not set. (including 2 remote controllers)	_	_
E02	0	٠	٠		Remote controller send error	Remote controller	Signal cannot be sent to indoor unit.		
E03	0	۲	•		Regular communication error between indoor and remote controller	Indoor	No communication from remote controller and network adapter	0	×
E04	•	•	0		Indoor/Outdoor serial error	Indoor	Serial communication error between indoor and outdoor	0	×
E08	0	•	۲		Duplicated indoor addresses	Indoor	Same address as yours was detected.	0	
E09	0	٠	٠		Duplicated main remote controllers	Remote controller	In 2-remote controller control, both were set as master. (Indoor master unit stops warning and follower unit continues operation.)	×	×
E10	0	۲	•		Communication error between CPU	Indoor	MCU communication error between main motor and micro computer	0	
E18	0	•	٠		Regular communication error between master and follower indoor units	Indoor	Regular communication was impossible between master and follower indoor units. Communication between twin master (Main unit) and follower (sub unit) was impossible.	0	×
L03	0	•	0	SIM	Duplicated indoor master units 🛛 🔶	Indoor	There are multiple master units in a group.	×	×
L07	0		0	SIM	There is group cable in individual indoor unit. 🛛 🔶	Indoor	When even one group connection indoor unit exists in individual indoor unit	×	×
L08	0	Õ	0	SIM	Unset indoor group address	Indoor	Indoor address group was unset.	×	×
L09	0	ě	0	SIM	Unset indoor capacity	Indoor	Capacity of indoor unit was unset.	×	×
L30	ø	ŏ	0	SIM	Outside error input to indoor unit (Interlock)	Indoor	Abnormal stop by CN80 outside error input	×	×
P19	0	•	0	ALT	4-way valve inverse error	Indoor Outdoor	In heating operation, error was detected by temp. down of indoor heat exchanger or temp. up ofTE, TS.	0	×

+ When this warning was detected before group construction/address check finish at power supply was turned on, the mode shifts automatically to AUTO address setup mode.



## Indoor Lamp Indication for Trouble Shooting - RAV Series

O : Go on, ⊚ : Flash, ● : Go off

ALT (Alternate): Alternate flashing when there are two flashing LED SIM (Simultaneous): Simultaneous flashing when there are two flashing LED

Remote	Ind	Indoor Sensor lamp part		Indoor Sensor lamp part		Indoor Sensor lamp part		part					
controller				Representative defective position	Detection	Explanation of error contents	Automatic reset	Operation continuation					
indication	Operatio	tion Timer Ready Flash		Flash				reset	continuation				
F01	0	0		ALT	Indoor unit Heat exchanger sensor (TCJ) error	Indoor	Open/Short of heat exchanger (TCJ) was detected.	0	×				
F02	0	0		ALT	Indoor unit Heat exchanger sensor (TC) error	Indoor	Open/Short of heat exchanger (TC) was detected.	0	×				
F10	0	0		ALT	Indoor unit Room temp. sensor (TA) error	Indoor	Open/Short of room temp. (TA) was detected.	0	×				
F29	0	0	•	SIM	Indoor unit Other indoor P.C. board error	Indoor	EEPROM error (Other error may be detected. If no error, automatic address is repeated.	×	×				
P01	•	0	0	ALT	Indoor unit Indoor fan error	Indoor	Indoor AC fan error was detected. (Fan thermal relay worked.)	×	×				
P10	•	0	0	ALT	Indoor unit Overflow detection	Indoor	Float switch worked.	×	×				
P12		0	0	ALT	Indoor unit Indoor fan error	Indoor	Indoor fan error (Over-current / Lock, etc.) was detected.	×	×				
P31	0		0	ALT	Other indoor unit error	Indoor	Other indoor under condition of warning in group. E03/L07/L03/L08 warning	0	×				
-	By un	it with war	rning No.	ALT	Error in indoor group	Network adapter	Sub remote controller error in a group (Details of remote controller are displayed with unit No. Only central control side is displayed.)		-				
_		—			LAN system communication error	Network adapter/ Center	Communication error of central control system signal * Is not displayed on the remote controller	0	0				
L20	0	0	0	SIM	LAN system communication error	Network adapter/ Center	Duplicated indoor address of central control system communication	0	×				
		-			There are multiple communication adapters.	Network adapter	There are multiple communication adapters on remote controller communication line.	0	0				

## Download **Toshiba Fault Codes** from your Apps Store or go to web page Toshiba-calc.co.uk/fault-codes/

Example: 1 Local controller displaying fault code **E04** Enter **E04** and select **Find Fault** 

VRF fault codes can be model specific and may require condenser model reference in Fault Code

Example: 2 Local controller displaying fault code L29 Condenser displaying sub-code 07 Model of condenser MMY-MAP1604HT8-E Enter L29071604 and select Find Fault

**Please note**; codes can be entered with or without character spaces, spaces ignored in text strings.

## Apps Store Fault Codes – All Commercial & VRF Systems





I code diagnosis apps now available For Apple (Phone & Android





## Fault Codes – All Commercial & VRF Systems

2

4

**<u>Do Not</u>** turn off the power supply before reading the fault codes, doing so will clear the diagnostic memory.

Caution must be taken when removing the access covers, as high voltages are present.

Fault diagnosis is available at four locations within the Air Conditioning system. :-

- 1 Remote Controller press the check button
- 3 Central Controller press the check button (if installed)

- Multi Controller rotate the display switch to position 1
- Outdoor Unit Switch position (variable dependent upon model): 2 Pipe Super Multi 2, 3 & 8; 3 Pipe SMI 2 & 0 2 Pipe SMMS, MMY 1, 1, 1 3 Pipe SHRM, MMY 1, 1, 1

Code	Fault Description
04	Split A/C equipment indoor to outdoor communication failure / VRF equipment could also be attributed to communication breakdown between
04	condenser PCB's. Likely cause Indoor PCB / condenser PCB / Interconnecting cable damage / transformer used to power condenser PCB
08	Reverse change in temperature. Detected by indoor evaporator sensor (TC). Likely cause 4-way valve. 4 way reversing valve energised for heating
00	operation only
09	Frost conditions detected / No temperature change. Detected indoors by evaporator sensor (TC). Likely cause poor airflow, lack of refrigerant,
05	overheating compressor
11	Indoor fan trouble. Detected indoors. Likely cause fan motor, PCB
12	EEPROM Failure on PCB. Detected indoors (replace indoor PCB)
14	Inverter compressor PCB short circuit. Detected at outdoor. Likely cause blown fuses supplying inverter pack, faulty IPDU(inverter board) or
14	component within inverter pack, electrical fault on inverter compressor
15	Multi-Control box error. Detected indoors (interrogate Multi-Control box for additional faults by setting display switch @ position 1)
17	Abnormal current detection on inverter compressor. Detected at outdoor. (replace IPDU PCB (inverter board))
18	Condenser coil sensor fault. Detected indoors. Likely cause TE/TE1 sensor condition or outdoor PCB fault sensor value 20°c=12.5k ohms
19	Liquid or compressor discharge sensor fault. Likely cause TL, TD sensor condition or PCB fault TL sensor value 20°c=12.5k ohms TD sensor value
	20°c=63k ohms
20	Condenser PCB faulty (replace main PCB)
	2 pipe VRF & Split A/C equipment High Pressure switch activation 425psi-29bar _ 3 pipe VRF equipment, interrogate condenser PCB for additional fault
21	code. Detected at outdoor. Likely cause split A/C equipment faulty H.P. switch, restriction in refrigerant flow, fan motor failure, poor airflows / VRF
	equipment set condenser interface PCB switches as follows SW1 @ position 2 & SW2 @ position 0 (see sub codes Er21 or ErAd)
22	Excessive high pressure. Detected at outdoor. Likely cause abnormal characteristics of Pd transducer, refrigerant restriction/blockage
80	Multi-Control box Th(A) sensor fault. Likely cause TH(A) sensor or M/C box PCB sensor value 20°c=12.5k ohms
81	Multi-Control box Th(B) sensor fault. Likely cause TH(B) sensor or M/C box PCB sensor value 20°c=12.5k ohms
82	Multi-Control box Th(C) sensor fault. Likely cause TH(C) sensor or M/C box PCB sensor value 20°c=12.5k ohms
83	Multi-Control box Th(D) sensor fault. Likely cause TH(D) sensor or M/C box PCB sensor value 20°c=12.5k ohms
84	Multi-Control box Th(X) sensor fault. Likely cause TH(X) sensor or M/C box PCB sensor value 20°c=12.5k ohms



Code	Fault Description
87	Phase missing phase. Detected at outdoor. Likely cause abnormal power supply
88	Multi-Control box does not recognise condenser capacity. Likely cause interconnecting cable damage, outdoor PCB fault
89	Indoor capacity to high. Likely cause loss of combination within group of modularised condensers
93	Indoor coil sensor fault. Detected indoors. Likely cause TC1 sensor condition or indoor PCB fault sensor value 20°c=12.5k ohms
94	Indoor coil sensor fault. Detected indoors. Likely cause TC2 sensor condition or indoor PCB fault sensor value 20°c=12.5k ohms
95	Communication failure on P&Q network (indoor/outdoor communication). Detected indoors & outdoors. Likely cause network cable condition, PCB failure indoor or outdoor
96	Indoor unit count too high. Detected at outdoor. Likely cause indoor capacity vs. outdoor capacity Incorrect, too many indoor units connected
97	Central control communication error. Detected at central controller & indoors. Likely cause indoor power failure, central address error, cable damage
98	Duplicated zone address. Likely cause incorrectly assigned central control addresses
99	No communication from indoor to remote controller. Detected by hard-wired remote controller. Likely cause faulty indoor PCB, remote controller or cable damage
0b	Indoor float switch open circuit as result of high condensation levels within drip tray. Detected indoors. Likely cause faulty float switch, faulty lift pump, debris blocking drain
<b>0</b> c	Return air sensor fault. Detected indoors. Likely cause TA sensor condition or indoor PCB fault sensor value 20°c=12.5k ohms
0d	Coil sensor fault. Detected indoors. Likely cause TC sensor condition or indoor PCB fault sensor value 20°c=12.5k ohms
1C	Outdoor error. Detected indoors (interrogate condenser for additional faults)
1d	High Inverter dc current. Detected at outdoor. Likely cause imbalance in compressor voltage, excessive amps by inverter compressor
1E	High compressor discharge temperature. Detected at outdoor. Likely cause low refrigerant, poor refrigerant flow, poor airflows, TD sensor condition sensor value 20°c=63k ohms
1F	High Inverter ac current. Detected at outdoor. Likely cause imbalance in compressor voltage, excessive amps by inverter compressor
8d	Outdoor unit quantity fallen (loss of communication between condensers). Detected at outdoor. Likely cause power interruption, BUS communication cable condition
8E	Outdoor unit's quantity too high. Detected at outdoor. Likely cause too many condensers connected
8F	Outdoor unit address incorrect. Detected at outdoor. Likely cause multiple modularised condenser having SW 9 ON, Interface PCB failure
9A	No temperature change on evaporator. Detected by indoor evaporator sensor TC1. Likely cause miss-wiring, restriction in refrigerant flow, lack of refrigerant
9F	Insufficient temperature change on evaporator. Detected indoors. Likely cause miss-wiring, restriction in refrigerant flow, lack of refrigerant, TC1, TC2 & TA sensor condition sensor value 20°c=12.5k ohms
A0	Compressor discharge sensor fault. Detected at outdoor. Likely cause TD1/ThD1 sensor condition or Interface PCB sensor value 20°c=63k ohms
A1	Compressor discharge sensor fault. Detected at outdoor. Likely cause TD2/ThD2 sensor condition or Interface PCB sensor value 20°c=63k ohms
A2	Compressor suction sensor fault. Detected at outdoor. Likely cause TS1/ThS sensor condition or interface PCB sensor value 20°c=12.5k ohms
A6	High compressor discharge temperature. Detected at outdoor. by TD1. Likely cause low refrigerant, poor refrigerant flow and airflows & TD2 sensor condition sensor value 20°c=63k ohms
A7	High compressor suction temperature > 40°C. Detected at outdoor. Likely cause severe gas shortage, TS sensor condition, interface PCB sensor value 20°c=12.5k ohms



AA       High side pressure sensor fault. Detected at outdoor. (Replace Pd pressure transducer)         Ab       Pressure transducer error. Detected at outdoor. Likely cause abnormal running pressures, abnormal PS / Pd         AE       High compressor discharge temperature @ low inverter speed. Detected at outdoor. Likely cause TD1 sensor value 20°c=63k ohms         AF       Phase rotation incorrect. Detected at outdoor. Likely cause abnormal phase order, missing phase to outdoor low pressure transducer error or misreading fault. Detected at outdoor. Likely cause incorrect characteristics interface PCB faulty         b5       External input activation, refrigerant leak detection system (Call Toshiba's technical helpline for further detail bf         b7       Indoor group follower error. Detected at outdoor. Likely cause evaporator pressure sensor unplugged, pressure sensor High compressor discharge temperature. Detected at outdoor. by TD2. Likely cause low refrigerant, poor ref         b8       Low pressure tring. Detected outdoor by PS transducer. Likely cause power loss at indoor unit group, networ         C06       Command receiving error. Detected at outdoor. Likely cause power loss at indoor unit group, networ         c1       Master condenser setup alarm. Detected at outdoor. Likely cause power loss at indoor unit group, networ         c3       Fault within follower condenser. Detected at outdoor. Likely cause power loss at indoor unit group, networ         c4       Oil sensor fault. Detected at outdoor. Likely cause multiple inverter outdoor unit group, networ         c56       Command r	
AE       High compressor discharge temperature @ low inverter speed. Detected at outdoor. Likely cause TD1 sensor value 20°c=63k ohms         AF       Phase rotation incorrect. Detected at outdoor. Likely cause abnormal phase order, missing phase to outdoor b4         Low pressure transducer error or misreading fault. Detected at outdoor. Likely cause incorrect characteristics interface PCB faulty         b5       External input activation, refrigerant leak detection system (Call Toshiba's technical helpline for further detail b6         External input activation, refrigerant leak detection system (Call Toshiba's technical helpline for further detail b7         D1       Indoor group follower error. Detected at central controller (interrogate local controller by pressing check for condition sensor value 20°c=63k ohms         bb       High compressor discharge temperature. Detected at outdoor. by TD2. Likely cause low refrigerant, poor refrigerant flow, lack of refrigerant         C05       Command sending error. Detected on Central Controller. Likely cause power loss at indoor unit group, netword of mander eceiving error. Detected on central Controller. Likely cause power loss at indoor unit group, netword of sensor fault. Detected at outdoor. Likely cause coddition of subtoor units connected, d2         G05       Command receiving error. Detected at outdoor. Likely cause condition or outdoor PCB fault sensor value 20         d1       Master condenser setup alarm. Detected at outdoor. Likely cause condition or outdoor PCB fault sensor value 20         d2       Fault within follower condenser. Detected at outdoor. Likely cause Condition or outdoor	
AE       value 20°c=63k ohms         AF       Phase rotation incorrect. Detected at outdoor. Likely cause abnormal phase order, missing phase to outdoor         b4       Low pressure transducer error or misreading fault. Detected at outdoor. Likely cause incorrect characteristics interface PCB faulty         b5       External input activation, refrigerant leak detection system (Call Toshiba's technical helpline for further detail         b6       External input activation, refrigerant leak detection system (Call Toshiba's technical helpline for further detail         b7       Indoor group follower error. Detected at controller (interrogate local controller by pressing check for condition sensor value 20°c=63k ohms         b8       Eversor discharge temperature. Detected at outdoor. by TD2. Likely cause low refrigerant, poor refr condition sensor value 20°c=63k ohms         b8       Low pressure trip. Detected outdoor by PS transducer. Likely cause suction pressure transducer condition (Prefrigerant flow, lack of refrigerant         c005       Command sending error. Detected on Central Controller. Likely cause power loss at indoor unit group, networ         c104       Master condenser setup alarm. Detected at outdoor. Likely cause ditional fault code from follower condenser         d1       Master condenser setup alarm. Detected at outdoor. Likely cause condition or outdoor PCB fault sensor value 20         d2       Fault within follower condenser. Detected at outdoor. Likely cause condition or outdoor PCB fault sensor value 20         d3       IPDU PCB overhea	characteristics, interface PCB
b4       Low pressure transducer error or misreading fault. Detected at outdoor. Likely cause incorrect characteristics interface PCB faulty         b5       External input activation, refrigerant leak detection system (Call Toshiba's technical helpline for further detail         b7       Indoor group follower error. Detected at central controller (interrogate local controller by pressing check for or orging pollower error. Detected at central controller (interrogate local controller by pressing check for condition sensor value 20°c=63k ohms         b8       Low pressure trip. Detected outdoor by PS transducer. Likely cause sensor unplugged, pressure sensor fault. Detected on Central Controller. Likely cause power loss at indoor unit group, networ condition sensor value 20°c=63k ohms         b8       Low pressure trip. Detected on Central Controller. Likely cause power loss at indoor unit group, networ C06         Command receiving error. Detected at outdoor. Likely cause multiple inverter outdoor unit group, networ d1         d1       Master condenser setup alarm. Detected at outdoor. Likely cause multiple inverter outdoor units connected, d2         fault within follower condenser. Detected at outdoor. Likely cause condition or outdoor PCB fault sensor value 20°c         d4       Oil sensor fault. Detected at outdoor. Likely cause TK1 sensor condition or outdoor PCB fault sensor value 20°c         d5       Oil sensor fault. Detected at outdoor. Likely cause TK1 sensor location or condition, interface PCB fault sensor value 20°c         d5       Oil sensor fault. Detected at outdoor. Likely cause TK1 sensor location or condition, outdoor PCB fau	r condition, insufficient refrigerant sensor
b4       interface PCB faulty         b5       External input activation, refrigerant leak detection system (Call Toshiba's technical helpline for further detail         b6       External input activation, refrigerant leak detection system (Call Toshiba's technical helpline for further detail         b7       Indoor group follower error. Detected at central controller (interrogate local controller by pressing check for -         b9       Pressure sensor fault. Detected indoors. Likely cause evaporator pressure sensor unplugged, pressure sensor condition sensor value 20°c=63k ohms         b6       Low pressure trip. Detected outdoor by PS transducer. Likely cause suction pressure transducer condition (Pt refrigerant flow, lack of refrigerant         C05       Command sending error. Detected on Central Controller. Likely cause power loss at indoor unit group, networe to condenser setup alarm. Detected at outdoor. Irely cause multiple inverter outdoor units connected, d1         d1       Fault within follower condenser. Detected at outdoor. Likely cause clogged heat-sink fins, poorly secured d4         01       sensor fault. Detected at outdoor. Likely cause TK1 sensor condition or outdoor PCB fault sensor value 20         d5       Oil sensor fault. Detected at outdoor. Likely cause TK1 sensor condition, outdoor PCB fault sensor value 20         d6       Oil sensor fault. Detected at outdoor. Likely cause TK1 sensor condition or condition, outdoor PCB fault sensor value 20         d6       Oil sensor fault. Detected at outdoor. Likely cause TK1 sensor location or condition, outdoor PCB fault senso	
b6         External input activation, refrigerant leak detection system (Call Toshiba's technical helpline for further detail           b7         Indoor group follower error. Detected at central controller (interrogate local controller by pressing check for one of the pressure sensor fault. Detected indoors. Likely cause evaporator pressure sensor unplugged, pressure sensor and the pressure sensor value 20°c=63k ohms           bb         High compressor discharge temperature. Detected at outdoor. by TD2. Likely cause low refrigerant, poor refrigerant flow, lack of refrigerant           C05         Command sending error. Detected on Central Controller. Likely cause power loss at indoor unit group, networe Co6           C06         Command sending error. Detected on Central Controller. Likely cause power loss at indoor unit group, networe Co6           d1         Master condenser setup alarm. Detected at outdoor. Likely cause multiple inverter outdoor units connected, oli sensor fault. Detected at outdoor. Likely cause multiple inverter outdoor units connected, oli sensor fault. Detected at outdoor. Likely cause TK1 sensor condition or outdoor PCB fault sensor value 20           d5         Oil sensor fault. Detected at outdoor. Likely cause TK3 sensor condition or outdoor PCB fault sensor value 20           d6         Oil sensor fault. Detected at outdoor. Likely cause TK1 sensor location or condition, outdoor PCB fault sensor value 20           d6         Oil sensor fault. Detected at outdoor. Likely cause TK1 sensor location or condition, outdoor PCB fault sensor value 20           d6         Oil sensor fault. Detected at outdoor. Likely cause TK1 sensor location or con	s of suction pressure transducer (PS,
<ul> <li>b7 Indoor group follower error. Detected at central controller (interrogate local controller by pressing check for b9 Pressure sensor fault. Detected indoors. Likely cause evaporator pressure sensor unplugged, pressure sensor condition sensor value 20°c=63k ohms</li> <li>bb High compressor discharge temperature. Detected at outdoor. by TD2. Likely cause low refrigerant, poor refrigerant flow, lack of refrigerant</li> <li>C05 Command sending error. Detected on Central Controller. Likely cause power loss at indoor unit group, networ C06 Command receiving error. Detected on Central Controller. Likely cause power loss at indoor unit group, networ C06 Command receiving error. Detected at outdoor. Likely cause multiple inverter outdoor units connected, a Fault within follower condenser. Detected at outdoor. Likely cause clogged heat-sink fins, poorly secured d1 IPDU PCB overheat (inverter board). Detected at outdoor. Likely cause clogged heat-sink fins, poorly secured d2 Gil sensor fault. Detected at outdoor. Likely cause TK1 sensor condition or outdoor PCB fault sensor value 20 d6 Oil sensor fault. Detected at outdoor. Likely cause TK1 sensor condition, interface PCB, lack of d8 Oil temperature alarm. Detected at outdoor. Likely cause TK3 sensor location or condition, outdoor PCB fault d9 Oil temperature alarm. Detected at outdoor. Likely cause TK3 sensor location or condition, outdoor PCB fault d9 Oil temperature alarm. Detected at outdoor. Likely cause TK3 sensor location or condition, interface PCB, lack of d8 Oil temperature alarm. Detected at outdoor. Likely cause TK3 sensor location or condition, interface PCB fault, value 20°c=63k ohms</li> <li>dc High temperature oil alarm. Detected at outdoor. Likely cause TK1 sensor condition, interface PCB fault, high value 20°c=63k ohms</li> <li>dd Temperature oil alarm. Detected at outdoor. Likely cause TK1 sensor condition, interface PCB fault, high value 20°c=63k ohms</li> </ul>	ils 0870 843 0333)
b9       Pressure sensor fault. Detected indoors. Likely cause evaporator pressure sensor unplugged, pressure sensor         bb       High compressor discharge temperature. Detected at outdoor. by TD2. Likely cause low refrigerant, poor refrigerant flow, lack of refrigerant         bE       Low pressure trip. Detected outdoor by PS transducer. Likely cause suction pressure transducer condition (PS refrigerant flow, lack of refrigerant         C05       Command sending error. Detected on Central Controller. Likely cause power loss at indoor unit group, network         d1       Master condenser setup alarm. Detected at outdoor. Likely cause multiple inverter outdoor units connected, at put within follower condenser. Detected at outdoor. Likely cause multiple inverter outdoor units connected, at IPDU PCB overheat (inverter board). Detected at outdoor. Likely cause condition or outdoor PCB fault sensor value 20         d5       Oil sensor fault. Detected at outdoor. Likely cause TK1 sensor condition or outdoor PCB fault sensor value 20         d6       Oil sensor fault. Detected at outdoor. Likely cause TK1 sensor condition or outdoor PCB fault sensor value 20         d6       Oil sensor fault. Detected at outdoor. Likely cause TK1 sensor condition or outdoor PCB fault sensor value 20         d7       Low oil detection. Detected at outdoor. Likely cause TK1 sensor condition or condition, outdoor PCB fault sensor value 20         d6       Oil sensor fault. Detected at outdoor. Likely cause TK1 sensor location or condition, outdoor PCB fault sensor value 20         d6       Oil temperature alarm. Detected at outdoor. Likely cause TK1	ils 0870 843 0333)
bb       High compressor discharge temperature. Detected at outdoor. by TD2. Likely cause low refrigerant, poor refrigerant is condition sensor value 20°c=63k ohms         bE       Low pressure trip. Detected outdoor by PS transducer. Likely cause suction pressure transducer condition (PS refrigerant flow, lack of refrigerant         C05       Command sending error. Detected on Central Controller. Likely cause power loss at indoor unit group, network         C06       Command receiving error. Detected on Central Controller. Likely cause power loss at indoor unit group, network         d1       Master condenser setup alarm. Detected at outdoor. Likely cause multiple inverter outdoor units connected, in the fourth of the present (inverter board). Detected at outdoor. Likely cause clogged heat-sink fins, poorly secured         d2       Fault within follower condenser. Detected at outdoor. Likely cause clogged heat-sink fins, poorly secured         d4       Oil sensor fault. Detected at outdoor. Likely cause TK1 sensor condition or outdoor PCB fault sensor value 20         d5       Oil sensor fault. Detected at outdoor. Likely cause TK2 sensor condition, or condition, outdoor PCB fault         d7       Low oil detection. Detected at outdoor. Likely cause TK1 sensor location or condition, outdoor PCB fault         d8       Oil temperature alarm. Detected at outdoor. Likely cause TK1 sensor condition, outdoor PCB fault         d6       Oil temperature alarm. Detected at outdoor. Likely cause TK1 sensor condition, outdoor PCB fault         d6       Oil temperature alarm. Detected at outdoor. Likely ca	additional fault codes)
bb       condition sensor value 20°c=63k ohms         bE       Low pressure trip. Detected outdoor by PS transducer. Likely cause suction pressure transducer condition (PS refrigerant flow, lack of refrigerant         C05       Command sending error. Detected on Central Controller. Likely cause power loss at indoor unit group, network         C06       Command receiving error. Detected on Central Controller. Likely cause power loss at indoor unit group, network         d1       Master condenser setup alarm. Detected at outdoor. Likely cause multiple inverter outdoor units connected,         d2       Fault within follower condenser. Detected at outdoor. Likely cause clogged heat-sink fins, poorly secured         d3       IPDU PCB overheat (inverter board). Detected at outdoor. Likely cause clogged heat-sink fins, poorly secured         d4       Oil sensor fault. Detected at outdoor. Likely cause TK1 sensor condition or outdoor PCB fault sensor value 20         d6       Oil sensor fault. Detected at outdoor. Likely cause TK3 sensor condition, interface PCB, lack of         d8       Oil temperature alarm. Detected at outdoor. Likely cause TK1 sensor location or condition, outdoor PCB fault         d9       Oil temperature alarm. Detected at outdoor. Likely cause TK1 sensor location or condition, outdoor PCB fault         d4       Oil temperature alarm. Detected at outdoor. Likely cause TK1 sensor location or condition, outdoor PCB fault         d7       Low oil detection. Detected at outdoor. Likely cause TK1 sensor location or condition, outdoor PCB fault	· · ·
DErefrigerant flow, lack of refrigerantCO5Command sending error. Detected on Central Controller. Likely cause power loss at indoor unit group, networC06Command receiving error. Detected on Central Controller. Likely cause power loss at indoor unit group, netword1Master condenser setup alarm. Detected at outdoor. Likely cause multiple inverter outdoor units connected,d2Fault within follower condenser. Detected at outdoor. Likely cause multiple inverter outdoor units connected,d3IPDU PCB overheat (inverter board). Detected at outdoor. Likely cause clogged heat-sink fins, poorly securedd4Oil sensor fault. Detected at outdoor. Likely cause TK1 sensor condition or outdoor PCB fault sensor value 20d5Oil sensor fault. Detected at outdoor. Likely cause TK3 sensor condition or outdoor PCB fault sensor value 20d6Oil sensor fault. Detected at outdoor. Likely cause TK1 sensor condition or outdoor PCB fault sensor value 20d6Oil sensor fault. Detected at outdoor. Likely cause TK1 sensor condition or outdoor PCB fault sensor value 20d7Low oil detection. Detected at outdoor. Likely cause TK1 sensor condition or condition, interface PCB, lack ofd8Oil temperature alarm. Detected at outdoor. Likely cause TK1 sensor location or condition, outdoor PCB faultd9Oil temperature alarm. Detected at outdoor. Likely cause TK1 sensor location or condition, outdoor PCB faultd4Abnormal overheat of heat-sink. Detected at outdoor. Likely cause TK1 sensor location or condition, interface PCB faultd9Oil temperature alarm. Detected at outdoor. Likely cause TK1 sensor location or condition, interfaced6Abnormal overheat of heat	-
C06Command receiving error. Detected on Central Controller. Likely cause power loss at indoor unit group, netwd1Master condenser setup alarm. Detected at outdoor. Likely cause multiple inverter outdoor units connected,d2Fault within follower condenser. Detected at outdoor. (retrieve additional fault code from follower condenserd3IPDU PCB overheat (inverter board). Detected at outdoor. Likely cause clogged heat-sink fins, poorly securedd4Oil sensor fault. Detected at outdoor. Likely cause TK1 sensor condition or outdoor PCB fault sensor value 20d5Oil sensor fault. Detected at outdoor. Likely cause TK2 sensor condition or outdoor PCB fault sensor value 20d6Oil sensor fault. Detected at outdoor. Likely cause TK1 sensor condition or outdoor PCB fault sensor value 20d7Low oil detection. Detected at outdoor. Likely cause TK1 sensor location or condition, interface PCB, lack ofd8Oil temperature alarm. Detected at outdoor. Likely cause TK1 sensor location or condition, outdoor PCB faultd9Oil temperature alarm. Detected at outdoor. Likely cause TK2 sensor location or condition, outdoor PCB faultd4Abnormal overheat of heat-sink. Detected at outdoor. Likely cause Clogged heat-sink fins, poorly secured ordbNo oil flow detected. Detected at outdoor. Likely cause TK1 sensor location or condition, interface PCB fault, interfacedbPoice=63k ohmsdcHigh temperature oil alarm. Detected at outdoor. Likely cause TK1 sensor condition, interface PCB fault, high value 20°c=63k ohmsddTemperature change when condensers in off cycle. Detected at outdoor. Likely cause PMV passing within con transducer error (PS & Pd characteristics), in	
d1Master condenser setup alarm. Detected at outdoor. Likely cause multiple inverter outdoor units connected,d2Fault within follower condenser. Detected at outdoor. (retrieve additional fault code from follower condenserd3IPDU PCB overheat (inverter board). Detected at outdoor. Likely cause clogged heat-sink fins, poorly securedd4Oil sensor fault. Detected at outdoor. Likely cause TK1 sensor condition or outdoor PCB fault sensor value 20d5Oil sensor fault. Detected at outdoor. Likely cause TK2 sensor condition or outdoor PCB fault sensor value 20d6Oil sensor fault. Detected at outdoor. Likely cause TK3 sensor condition or outdoor PCB fault sensor value 20d7Low oil detection. Detected at outdoor. Likely cause TK1 sensor location or condition, interface PCB, lack ofd8Oil temperature alarm. Detected at outdoor. Likely cause TK1 sensor location or condition, outdoor PCB faultd9Oil temperature alarm. Detected at outdoor. Likely cause TK2 sensor location or condition, outdoor PCB faultd4Abnormal overheat of heat-sink. Detected at outdoor. Likely cause TK2 sensor location or condition, outdoor PCB faultd9Oil temperature alarm. Detected at outdoor. Likely cause TK2 sensor location or condition, outdoor PCB faultd4Abnormal overheat of heat-sink. Detected at outdoor. Likely cause TK1 sensor location or condition, interface PCB faultd6Oil temperature oil alarm. Detected at outdoor. Likely cause TK1 sensor location or condition, interfaced6No oil flow detected. Detected at outdoor. Likely cause TK1 sensor condition, interface PCB fault, interfaced0No oil flow detected. Detected at outdoor. Likely cause TK1 sensor condition, inte	ork cable condition)
d2Fault within follower condenser. Detected at outdoor. (retrieve additional fault code from follower condenserd3IPDU PCB overheat (inverter board). Detected at outdoor. Likely cause clogged heat-sink fins, poorly securedd4Oil sensor fault. Detected at outdoor. Likely cause TK1 sensor condition or outdoor PCB fault sensor value 20d5Oil sensor fault. Detected at outdoor. Likely cause TK2 sensor condition or outdoor PCB fault sensor value 20d6Oil sensor fault. Detected at outdoor. Likely cause TK3 sensor condition or outdoor PCB fault sensor value 20d7Low oil detection. Detected at outdoor. Likely cause TK1 sensor condition or outdoor PCB fault sensor value 20d8Oil temperature alarm. Detected at outdoor. Likely cause TK1 sensor location or condition, outdoor PCB faultd9Oil temperature alarm. Detected at outdoor. Likely cause TK2 sensor location or condition, outdoor PCB faultd4Abnormal overheat of heat-sink. Detected at outdoor. Likely cause TK2 sensor location or condition, outdoor PCB faultd9Oil temperature alarm. Detected at outdoor. Likely cause TK1 sensor location or condition, outdoor PCB faultd9Oil temperature alarm. Detected at outdoor. Likely cause TK2 sensor location or condition, interface PCB faultd8Oil flow detected. Detected at outdoor. Likely cause TK1, TK2 & TK3 sensor location or condition, interface PCB faultd9Oil temperature oil alarm. Detected at outdoor. Likely cause TK1, TK2 & TK3 sensor location or condition, interface PCB faultd6No oil flow detected. Detected at outdoor. Likely cause TK1, TK2 & TK3 sensor location or condition, interface PCB faultd0Temperature oil alarm. Detected at outdoor. Li	vork cable condition)
d3IPDU PCB overheat (inverter board). Detected at outdoor. Likely cause clogged heat-sink fins, poorly securedd4Oil sensor fault. Detected at outdoor. Likely cause TK1 sensor condition or outdoor PCB fault sensor value 20d5Oil sensor fault. Detected at outdoor. Likely cause TK2 sensor condition or outdoor PCB fault sensor value 20d6Oil sensor fault. Detected at outdoor. Likely cause TK3 sensor condition or outdoor PCB fault sensor value 20d7Low oil detection. Detected at outdoor. Likely cause TK1 sensor condition or outdoor PCB fault sensor value 20d7Low oil detection. Detected at outdoor. Likely cause TK1 sensor condition, interface PCB, lack ofd8Oil temperature alarm. Detected at outdoor. Likely cause TK1 sensor location or condition, outdoor PCB faultd9Oil temperature alarm. Detected at outdoor. Likely cause TK2 sensor location or condition, outdoor PCB faultd4Abnormal overheat of heat-sink. Detected at outdoor. Likely cause TK2 sensor location or condition, outdoor PCB faultd8Oil temperature alarm. Detected at outdoor. Likely cause TK2 sensor location or condition, outdoor PCB faultd9Oil temperature alarm. Detected at outdoor. Likely cause TK1 sensor location or condition, interfacedbNo oil flow detected. Detected at outdoor. Likely cause TK1, TK2 & TK3 sensor location or condition, interfacedbNo oil flow detected. Detected at outdoor. Likely cause TK1, TK2 & TK3 sensor location or condition, interfacedcNo oil flow detected. Detected at outdoor. Likely cause TK1 sensor condition, interface PCB fault, high value 20°c=63k ohmsddTemperature oil alarm. Detected at outdoor. Likely cause TK1 sensor condition, inte	faulty interface PCB)
d4Oil sensor fault. Detected at outdoor. Likely cause TK1 sensor condition or outdoor PCB fault sensor value 20d5Oil sensor fault. Detected at outdoor. Likely cause TK2 sensor condition or outdoor PCB fault sensor value 20d6Oil sensor fault. Detected at outdoor. Likely cause TK3 sensor condition or outdoor PCB fault sensor value 20d7Low oil detection. Detected at outdoor. Likely cause TK3 sensor condition or outdoor PCB fault sensor value 20d7Low oil detection. Detected at outdoor. Likely cause TK1 sensor condition or outdoor PCB fault sensor value 20d8Oil temperature alarm. Detected at outdoor. Likely cause TK1 sensor location or condition, interface PCB, lack ofd8Oil temperature alarm. Detected at outdoor. Likely cause TK2 sensor location or condition, outdoor PCB faultd9Oil temperature alarm. Detected at outdoor. Likely cause TK2 sensor location or condition, outdoor PCB faultd8Oil temperature alarm. Detected at outdoor. Likely cause TK2 sensor location or condition, outdoor PCB faultd9Oil temperature alarm. Detected at outdoor. Likely cause TK1 sensor location or condition, interface PCB faultd8Oil flow detected. Detected at outdoor. Likely cause TK1, TK2 & TK3 sensor location or condition, interfacedbNo oil flow detected. Detected at outdoor. Likely cause TK1, TK2 & TK3 sensor condition, interface PCB fault, high value 20°c=63k ohmsd6Temperature oil alarm. Detected at outdoor. Likely cause TK1 sensor condition, interface PCB fault, high value 20°c=63k ohmsd6Temperature change when condensers in off cycle. Detected at outdoor. Likely cause PMV passing within contransducer error (PS & Pd characteristics), interface PCB fault </th <th>,</th>	,
d5Oil sensor fault. Detected at outdoor. Likely cause TK2 sensor condition or outdoor PCB fault sensor value 20d6Oil sensor fault. Detected at outdoor. Likely cause TK3 sensor condition or outdoor PCB fault sensor value 20d7Low oil detection. Detected at outdoor. Likely cause TK1, TK2 & TK3 sensor condition, interface PCB, lack ofd8Oil temperature alarm. Detected at outdoor. Likely cause TK1 sensor location or condition, outdoor PCB faultd9Oil temperature alarm. Detected at outdoor. Likely cause TK2 sensor location or condition, outdoor PCB faultd4Abnormal overheat of heat-sink. Detected at outdoor. Likely cause TK1 sensor location or condition, outdoor PCB faultdbNo oil flow detected. Detected at outdoor. Likely cause TK1, TK2 & TK3 sensor location or condition, interface PCB faultdbNo oil flow detected. Detected at outdoor. Likely cause TK1, TK2 & TK3 sensor location or condition, interfacedCNo oil flow detected. Detected at outdoor. Likely cause TK1 sensor condition, interface PCB fault, high value 20°c=63k ohmsddTemperature oil alarm. Detected at outdoor. Likely cause TK1 sensor condition, interface PCB fault, high value 20°c=63k ohmsddTemperature change when condensers in off cycle. Detected at outdoor. Likely cause PMV passing within condition transducer error (PS & Pd characteristics), interface PCB fault	· · · · · ·
d6Oil sensor fault. Detected at outdoor. Likely cause TK3 sensor condition or outdoor PCB fault sensor value 20d7Low oil detection. Detected at outdoor. Likely cause TK1, TK2 & TK3 sensor condition, interface PCB, lack ofd8Oil temperature alarm. Detected at outdoor. Likely cause TK1 sensor location or condition, outdoor PCB faultd9Oil temperature alarm. Detected at outdoor. Likely cause TK2 sensor location or condition, outdoor PCB faultdAAbnormal overheat of heat-sink. Detected at outdoor. Likely cause TK2 sensor location or condition, outdoor PCB faultdbNo oil flow detected. Detected at outdoor. Likely cause TK1, TK2 & TK3 sensor location or condition, interface 20°c=63k ohmsdCHigh temperature oil alarm. Detected at outdoor. Likely cause TK1 sensor condition, interface PCB fault, high value 20°c=63k ohmsddTemperature oil alarm. Detected at outdoor. Likely cause TK1 sensor condition, interface PCB fault, high value 20°c=63k ohmsddHigh temperature oil alarm. Detected at outdoor. Likely cause TK1 sensor condition, interface PCB fault, high value 20°c=63k ohmsddTemperature change when condensers in off cycle. Detected at outdoor. Likely cause PMV passing within con transducer error (PS & Pd characteristics), interface PCB fault	,
d7Low oil detection. Detected at outdoor. Likely cause TK1, TK2 & TK3 sensor condition, interface PCB, lack ofd8Oil temperature alarm. Detected at outdoor. Likely cause TK1 sensor location or condition, outdoor PCB faultd9Oil temperature alarm. Detected at outdoor. Likely cause TK2 sensor location or condition, outdoor PCB faultdAAbnormal overheat of heat-sink. Detected at outdoor. Likely cause Clogged heat-sink fins, poorly secured ordbNo oil flow detected. Detected at outdoor. Likely cause TK1, TK2 & TK3 sensor location or condition, interfacedbNo oil flow detected. Detected at outdoor. Likely cause TK1, TK2 & TK3 sensor location or condition, interfacedbNo oil flow detected. Detected at outdoor. Likely cause TK1, TK2 & TK3 sensor location or condition, interfacedbNo oil flow detected. Detected at outdoor. Likely cause TK1, TK2 & TK3 sensor location or condition, interfacedCHigh temperature oil alarm. Detected at outdoor. Likely cause TK1 sensor condition, interface PCB fault, high value 20°c=63k ohmsddTemperature change when condensers in off cycle. Detected at outdoor. Likely cause PMV passing within contransducer error (PS & Pd characteristics), interface PCB fault	
d8       Oil temperature alarm. Detected at outdoor. Likely cause TK1 sensor location or condition, outdoor PCB fault         d9       Oil temperature alarm. Detected at outdoor. Likely cause TK2 sensor location or condition, outdoor PCB fault         dA       Abnormal overheat of heat-sink. Detected at outdoor. Likely cause Clogged heat-sink fins, poorly secured or the temperature of the temperature alarm. Detected at outdoor. Likely cause Clogged heat-sink fins, poorly secured or the temperature of temperature change when condensers in off cycle. Detected at outdoor. Likely cause PMV passing within contransducer error (PS & Pd characteristics), interface PCB fault	
d9       Oil temperature alarm. Detected at outdoor. Likely cause TK2 sensor location or condition, outdoor PCB fault         dA       Abnormal overheat of heat-sink. Detected at outdoor. Likely cause clogged heat-sink fins, poorly secured or         db       No oil flow detected. Detected at outdoor. Likely cause TK1, TK2 & TK3 sensor location or condition, interface 20°c=63k ohms         dC       High temperature oil alarm. Detected at outdoor. Likely cause TK1 sensor condition, interface PCB fault, high value 20°c=63k ohms         dd       Temperature change when condensers in off cycle. Detected at outdoor. Likely cause PMV passing within contransducer error (PS & Pd characteristics), interface PCB fault	<b>.</b>
dA       Abnormal overheat of heat-sink. Detected at outdoor. Likely cause clogged heat-sink fins, poorly secured or         db       No oil flow detected. Detected at outdoor. Likely cause TK1, TK2 & TK3 sensor location or condition, interface         20°c=63k ohms       High temperature oil alarm. Detected at outdoor. Likely cause TK1 sensor condition, interface PCB fault, high value 20°c=63k ohms         dd       Temperature change when condensers in off cycle. Detected at outdoor. Likely cause PMV passing within contransducer error (PS & Pd characteristics), interface PCB fault	
db       No oil flow detected. Detected at outdoor. Likely cause TK1, TK2 & TK3 sensor location or condition, interface 20°c=63k ohms         dC       High temperature oil alarm. Detected at outdoor. Likely cause TK1 sensor condition, interface PCB fault, high value 20°c=63k ohms         dd       Temperature change when condensers in off cycle. Detected at outdoor. Likely cause PMV passing within contransducer error (PS & Pd characteristics), interface PCB fault	
db       20°c=63k ohms         dC       High temperature oil alarm. Detected at outdoor. Likely cause TK1 sensor condition, interface PCB fault, high value 20°c=63k ohms         dd       Temperature change when condensers in off cycle. Detected at outdoor. Likely cause PMV passing within contransducer error (PS & Pd characteristics), interface PCB fault	
dc       value 20°c=63k ohms         dd       Temperature change when condensers in off cycle. Detected at outdoor. Likely cause PMV passing within contransducer error (PS & Pd characteristics), interface PCB fault	
transducer error (PS & Pd characteristics), interface PCB fault	h ambient running conditions >43°c sensor
	ndenser, discharge & suction pressure
dE Indoor unit automatic addressing failure. Detected at outdoor. Likely cause indoor PCB configuration error, ir	ndoor PCB faulty
dF Outdoor unit automatic address failure. Detected at outdoor. Likely cause interface PCB fault	



Code	Fault Description
E01	Communication error between indoor unit and remote controller. Detected by remote controller. Likely cause indoor PCB, remote controller, incorrect
	switch position on rear of remote controller, all switches normally down
E02	Sending error of local remote controller. Detected by remote controller. Likely cause replace remote controller
E03	Communication error between indoor unit and central remote controller. Detected indoors. Likely cause indoor network adapter, central remote controller
E04	Communication failure between indoor and outdoor units. Detected indoors. Likely cause split A/C=indoor PCB, outdoor PCB, interconnecting cable condition, compressor klixon open circuit. VRF system=power loss at condenser, U1/U2 network cable condition
E06	Decrease in quantity of indoor units. Detected indoors. Likely cause power loss at indoor unit, indoor PCB fault, A&B controller cable condition
E07	Communication failure between indoor and outdoor units. Detected at outdoor. Likely cause interconnecting cable condition, outdoor PCB switch position SW30 bit 1 & 2 must be placed in ON position for test
E08	Duplicated indoor address. Detected indoors. Likely cause incorrect setting of BUS addresses when under central control
E09	Duplicated master remote controllers. Detected indoors. Likely cause two local remote controller connected on A&B network
E1	Activation of high pressure switch on D.O.L (Fixed speed) compressor 1. Detected at outdoor. Likely cause fan motor trouble, poor airflows, restricted refrigerant flow
e1 80	Multi-Control box 1 Th(A) sensor fault. Likely cause TH(A) sensor or M/C box PCB sensor value 20°c=12.5k ohms
e1 81	Multi-Control box 1 Th(B) sensor fault. Likely cause TH(B) sensor or M/C box PCB sensor value 20°c=12.5k ohms
e1 82	Multi-Control box 1 Th(C) sensor fault. Likely cause TH(C) sensor or M/C box PCB sensor value 20°c=12.5k ohms
e1 83	Multi-Control box 1 Th(D) sensor fault. Likely cause TH(D) sensor or M/C box PCB sensor value 20°c=12.5k ohms
e1 84	Multi-Control box 1 Th(X) sensor fault. Likely cause TH(X) sensor or M/C box PCB sensor value 20°c=12.5k ohms
E10	Communication Error at indoor PCB. Detected indoors. Likely cause replace indoor PCB
E12	Automatic addressing error. Detected at outdoor. Likely cause incorrect self-addressing sequence, repeat self-addressing procedure. Retrieve fault sub- code from condenser interface PCB by placing rotary dials to position 1 / 1 / 1 for diagnosis.
E12 01	Automatic addressing error. Detected at outdoor. Indoor / Outdoor communication
E12 02	Automatic addressing error. Detected at outdoor. Outdoor / Outdoor communication
E15	Automatic self-addressing failure. Detected at outdoor. Likely cause SW30 bit 1 & 2 in OFF position, switch both ON before self-addressing commenced, interface PCB failure
E16	Indoor unit count or capacity to high. Detected at outdoor. Likely cause if condenser PCB displays sub code 00=indoor capacity vs. condenser to high. If sub code at condenser reads 01=indoor unit count/quantity to high. Retrieve fault sub-code from condenser interface PCB by placing rotary dials to position 1 / 1 / 1 for diagnosis.
E16 00	Indoor unit capacity to high. Detected at outdoor. Likely cause indoor unit capacity to high vs. condenser capacity
E16 01	Indoor unit count to high. Detected at outdoor. Likely cause indoor unit count to high vs. outdoor upper limit
E18	Communication failure between indoor units. Detected indoors. Likely cause indoor power loss, A&B controller cable condition. Twin, triple & Quad applications E18 can result from E04 fault code
E19	Outdoor header error. Detected at outdoor. Likely cause if condenser PCB displays sub code 00=power loss to indoor units or U1/U2 network cable condition. If sub code reads 01=incorrect wiring between modularised condensers. Retrieve fault sub-code from condenser interface PCB by placing rotary dials to position 1 / 1 / 1 for diagnosis.



Code	Fault Description
E19 00	Outdoor header error. Detected at outdoor. Likely cause power loss to indoor units, U1/U2 network cable condition, SW30 bit 1 & 2 must be ON to test
E19 01	Outdoor header error. Detected at outdoor. Likely cause incorrect wiring between modularised condensers
e2 80	Multi-Control box 2 Th(A) sensor fault. Likely cause TH(A) sensor or M/C box PCB sensor value 20°c=12.5k ohms
e2 81	Multi-Control box 2 Th(B) sensor fault. Likely cause TH(B) sensor or M/C box PCB sensor value 20°c=12.5k ohms
e2 82	Multi-Control box 2 Th(C) sensor fault. Likely cause TH(C) sensor or M/C box PCB sensor value 20°c=12.5k ohms
e2 83	Multi-Control box 2 Th(D) sensor fault. Likely cause TH(D) sensor or M/C box PCB sensor value 20°c=12.5k ohms
e2 84	Multi-Control box 2 Th(X) sensor fault. Likely cause TH(X) sensor or M/C box PCB sensor value 20°c=12.5k ohms
E20	One or more systems connected on network during self-addressing procedure. Detected at outdoor. Likely cause if condenser PCB displays sub code 01=multiple outdoor systems connected on U3/U4 network, miss-wiring or central control relay connecter in-place. If sub code reads 02=indoor units from other line connected, miss-wiring or central control relay connecter in-place. Retrieve fault sub-code from condenser interface PCB by placing rotary dials to position 1 / 1 / 1 for diagnosis.
E20 01	Multiple indoor system line numbers connected on network during self-addressing procedure. Detected at outdoor. Likely cause miss-wiring of indoor network cable, central control relay connecter together during self-address
E20 02	Multiple outdoor system numbers connected on network during self-address procedure. Detected at outdoor. Likely cause miss-wiring of outdoor units, central control relay/plug connected during self-address
E23	Communication error between outdoor units. Detect outdoors. Likely cause U5/U6 cable condition, interface PCB fault
E25	Duplicated follower outdoor unit address. Detected at outdoor. Likely cause error in manually assigning addresses, allow system to self-address
E26	Decrease in quantity of outdoor units connected. Detected at outdoor. Likely cause power loss at condensers, U5/U6 cable condition
E28	Outdoor follower fault. Detected at outdoor. Likely cause lead condenser OK, follower condenser has suffered fault, retrieve second fault code from follower condenser
E31	IPDU/PCB board communication error. Detected at outdoor. Likely cause loss in communication between condenser PCB's. Retrieve fault sub-code from condenser interface PCB by placing rotary dials to position $1 / 1 / 1$ for diagnosis.
E31 01	Compressor 1 IPDU board communication error. Detected at outdoor. Likely cause check communication cable linking all PCB's, replace Compressor 1 IPDU board
E31 02	Compressor 2 IPDU board communication error. Detected at outdoor. Likely cause check communication cable linking all PCB's, replace Compressor 2 IPDU board
E31 03	Compressor 1 & 2 IPDU board communication error. Detected at outdoor. Likely cause check communication cable linking all PCB's, replace Compressor 1 & 2 IPDU board
E31 04	Communication failure between PCB's within condenser. Detected at outdoor. Fault Code is outdoor model series specific e.g. MMY-MAP###1HT8-E, MMY-AP###2HT8-E or MMY-MAP###4HT8-E therefore example fault code for E3104 will be (MMY-MAP0801HT8-E (series 1), MMY-MAP0802HT8-E (series 2), MMY-MAP0804HT8-E (series 4) search E31041, E31042 or E31044
E31 04 1	Fan IPDU board communication error. Detected at outdoor. Likely cause check communication cable linking all PCB's, replace fan IPDU board
E31 04 2	Fan IPDU board communication error. Detected at outdoor. Likely cause check communication cable linking all PCB's, replace fan IPDU board
E31 04 4	Compressor 3 IPDU board communication error. Detected at outdoor. Likely cause check communication cable linking all PCB's, replace Compressor 3 IPDU board



Code	Fault Description
E31 05	Communication failure between PCB within condenser. Fault Code is outdoor model series specific e.g. MMY-MAP###1HT8-E, MMY-AP###2HT8-E or MMY-MAP###4HT8-E therefore example fault code for E3105 will be (MMY-MAP0801HT8-E (series 1), MMY-MAP0802HT8-E (series 2), MMY-MAP0804HT8-E (series 4) search E31051, E31052 or E31054
E31 05 <mark>1</mark>	Compressor 1 IPDU & fan IPDU board communication error. Detected at outdoor. Likely cause check communication cable linking all PCB's, replace Compressor 1 IPDU & fan IPDU board
E31 05 <mark>2</mark>	Compressor 1 IPDU & fan IPDU board communication error. Detected at outdoor. Likely cause check communication cable linking all PCB's, replace Compressor 1 IPDU & fan IPDU board
E31 05 <mark>4</mark>	Compressor 1 & 3 IPDU board communication error. Detected at outdoor. Likely cause check communication cable linking all PCB's, replace Compressor 1 & 3 IPDU board
E31 06	Communication failure between PCB within condenser. Detected at outdoor. Fault Code is outdoor model series specific e.g. MMY-MAP###1HT8-E, MMY-AP###2HT8-E or MMY-MAP###4HT8-E therefore example fault code for E3106 will be (MMY-MAP0801HT8-E (series 1), MMY-MAP0802HT8-E (series 2), MMY-MAP0804HT8-E (series 4) search E3101, E31062 or E31064
E31 06 <mark>1</mark>	Compressor 2 IPDU & fan IPDU board communication error. Detected at outdoor. Likely cause check communication cable linking all PCB's, replace Compressor 2 IPDU & fan IPDU board
E31 06 <mark>2</mark>	Compressor 2 IPDU & fan IPDU board communication error. Detected at outdoor. Likely cause check communication cable linking all PCB's, replace Compressor 2 IPDU & fan IPDU board
E31 06 <mark>4</mark>	Compressor 2 & 3 IPDU board communication error. Detected at outdoor. Likely cause check communication cable linking all PCB's, replace Compressor 2 & 3 IPDU board
E31 07	Communication failure between PCB within condenser. Detected at outdoor. (4 Series Condenser Compressor 1, 2 & 3 IPDU board communication error). (1&2 Series condenser communication error between PCB within condenser) likely cause phase missing on power supply, replace interface PCB
E31 07 <mark>1</mark>	Communication error between PCB within condenser. Detected at outdoor. Likely cause check communication cable linking all PCB's, phase missing on power supply, replace interface PCB
E31 07 <mark>2</mark>	Communication error between PCB within condenser. Detected at outdoor. Likely cause check communication cable linking all PCB's, phase missing on power supply, replace interface PCB
E31 07 <mark>4</mark>	Compressor 1, 2 & 3 IPDU board communication error. Detected at outdoor. Likely cause check communication cable linking all PCB's, replace Compressor 1, 2 & 3 IPDU board
E31 08	Fan IPDU board communication error. Detected at outdoor. Likely cause check communication cable linking all PCB's, replace fan IPDU board
E31 09	Compressor 1 IPDU & fan IPDU board communication error. Detected at outdoor. Likely cause check communication cable linking all PCB's, replace Compressor 1 IPDU & fan IPDU board
E31 0A	Compressor 2 IPDU & fan IPDU board communication error. Detected at outdoor. Likely cause check communication cable linking all PCB's, replace Compressor 2 IPDU & fan IPDU board
E31 0B	Compressor 1 & 2 IPDU board & fan IPDU board communication error. Detected at outdoor. Likely cause check communication cable linking all PCB's, replace Compressor 1 & 2 IPDU PCB & fan IPDU board
E31 0C	Compressor 3 IPDU board & fan IPDU board communication error. Detected at outdoor. Likely cause check communication cable linking all PCB's, replace Compressor 3 IPDU board & fan IPDU board
E31 0d	Compressor 1 & 3 IPDU board & fan IPDU board communication error. Detected at outdoor. Likely cause check communication cable linking all PCB's, replace Compressor 1 & 3 IPDU board & fan IPDU board



Code	Fault Description
E31 0E	Compressor 2 & 3 IPDU board & fan IPDU board communication error. Detected at outdoor. Likely cause check communication cable linking all PCB's,
	replace Compressor 2 & 3 IPDU PCB & fan IPDU board
E31 0F	Communication error between PCB within condenser. Detected at outdoor. Likely cause check communication cable linking all PCB's, phase missing on
	power supply, replace interface PCB
E5	Activation of high pressure switch or internal overheat (klixon on INVERTER compressor only. Detected at outdoor. Likely cause fan motor trouble,
	poor airflows, poor refrigerant flow, insufficient refrigerant
E6	Activation of compressor klixon or contactor overload on D.O.L (Fixed speed compressor 1. Detected at outdoor. Likely cause poor refrigerant flow,
	insufficient refrigerant, excessive amps by compressor
Eb	Resulting from b6 fault code generated at indoor unit. Detected at outdoor. (b6=External input activation, refrigerant leak detection system (Call
-	Toshiba's technical helpline for further details 0870 843 0333)
Er 14	Inverter compressor low voltage. Detected at outdoor. Likely cause AC fuse disconnection, faulty component within compressor inverter circuit,
En 4 d	electrical failure of compressor
Er 1d	High Inverter dc current. Detected at outdoor. Likely cause imbalance in compressor voltage, excessive amps by inverter compressor
Er 21	Inverter compressor trip. Detected at outdoor. Likely cause activation of high pressure switch 425psi-29bar / internal overheat (klixon) on inverter compressor only
Er A0	Compressor discharge sensor fault. Detected at outdoor. Likely cause TD1/ThD1 sensor condition or Interface PCB sensor value 20°c=63k ohms
Er AU	Compressor discharge sensor fault. Detected at outdoor. Likely cause TD2/ThD2 sensor condition or Interface PCB sensor value 20 c=03k ohms Compressor discharge sensor fault. Detected at outdoor. Likely cause TD2/ThD2 sensor condition or Interface PCB sensor value 20 c=63k ohms
Er A2	Compressor suction sensor fault. Detected at outdoor. Likely cause TD2/ThD2 sensor condition or interface PCB sensor value 20°c=12.5k ohms
Er A4	Ambient air sensor fault. Detected at outdoor. Likely cause Th0 sensor condition or interface PCB sensor value 20°c=12.5k ohms
Er A5	Condenser coil sensor fault. Detected at outdoor. Likely cause ThE sensor condition or interface PCB fault sensor value 20°c=12.5k ohms
	High compressor discharge temperature. Detected at outdoor. by TD1, TD2, ThD1 & ThD2. Likely cause low refrigerant, poor refrigerant flow and
Er A6	airflows & TD sensor condition sensor value 20°c=63k ohms
Er A7	High compressor suction temperature > 40°C. Detected at outdoor. Likely cause severe gas shortage, TS sensor condition, interface PCB sensor value
	20°c=12.5k ohms
Er AA	High side pressure sensor fault. Detected at outdoor. (Replace Pd pressure sensor)
Er Ad	Fixed speed compressor trip (D.O.L). Detected at outdoor. Likely cause activation of high pressure switch 425psi-29bar / internal overheat (klixon) /
Er Ad	phase rotation PCB / D.O.L contactor overload trip
Er AE	Low Pressure trip < 3 psig. Detected at outdoor. by L.P. switch. Likely cause refrigerant loss, restriction in refrigerant flow
Er AF	Phase rotation incorrect. Detected at outdoor. Likely cause abnormal phase order, missing phase to outdoor unit
F0	Activation of high pressure switch on D.O.L (Fixed speed) compressor 2. Detected at outdoor. Likely cause fan motor trouble, poor airflows, restricted
ΓU	refrigerant flow
F01	TCj Coil sensor fault. Detected indoors. Likely cause TCj sensor condition or indoor PCB fault sensor value 20°c=12.5k ohms
F02	TC2 or TC Coil sensor fault. Detected indoors. Likely cause TC2 / TC sensor condition or indoor PCB fault sensor value 20°c=12.5k ohms
F03	TC1 Coil sensor fault. Detected indoors. Likely cause TC1 sensor condition or indoor PCB fault sensor value 20°c=12.5k ohms



Code	Fault Description
F04	Td1 sensor fault. Detected at outdoor. Likely cause compressor discharge sensor condition (Td1) or outdoor PCB fault sensor value 20°c=63k ohms
F05	Td2 sensor fault. Detected at outdoor. Likely cause compressor discharge sensor condition (Td2) or outdoor PCB fault sensor value 20°c=63k ohms
F06	TE or TS Sensor fault. Detected at outdoor. Likely cause Heat exchange sensor condition (TE / TE1 / TE2). Suction line sensor condition (TS) or outdoor PCB fault sensor value 20°c=12.5k ohms. Retrieve fault sub-code from condenser interface PCB by placing rotary dials to position 1 / 1 / 1 for diagnosis.
F06 01	TE1 Sensor fault. Detected at outdoor. Likely cause Heat exchange sensor condition (TE1) or outdoor PCB fault sensor value 20°c=12.5k ohms
F06 02	TE2 Sensor fault. Detected at outdoor. Likely cause Heat exchange sensor condition (TE2) or outdoor PCB fault sensor value 20°c=12.5k ohms
F07	TL Sensor fault. Detected at outdoor. Likely cause Liquid line sensor condition (TL) or outdoor PCB fault sensor value 20°c=12.5k ohms
F08	TO Sensor fault. Detected at outdoor. Likely cause Ambient air sensor condition (TO) or outdoor PCB fault sensor value 20°c=12.5k ohms
F1	Activation of compressor klixon or contactor overload on D.O.L (Fixed speed compressor 2). Detected at outdoor. Likely cause poor refrigerant flow, insufficient refrigerant, excessive amps by compressor
F10	TA Sensor fault. Detected indoors. Likely cause Return air sensor condition (TA) or indoor PCB fault sensor value 20°c=12.5k ohms
F12	TS Sensor fault. Detected at outdoor. Likely cause Suction line sensor condition (TS / TS1 / TS2) or outdoor PCB fault sensor value 20°c=12.5k ohms
F13	Compressor IPDU board overheat. Detected at outdoor. Likely cause poor contact to heat-sink, IPDU board fault. Fault sub-code required to determine which board has suffered overheat 01=IPDU1 overheated 02=IPDU2 overheated 03=IPDU3 overheated. Retrieve fault sub-code from condenser
	interface PCB by placing rotary dials to position 1 / 1 / 1 for diagnosis.
F13 01	Compressor 1 IPDU board overheat. Detected at outdoor. Likely cause poor contact to heat-sink, replace compressor IPDU board 1
F13 02	Compressor 2 IPDU board overheat. Detected at outdoor. Likely cause poor contact to heat-sink, replace compressor IPDU board 2
F13 03	Compressor 3 IPDU board overheat. Detected at outdoor. Likely cause poor contact to heat-sink, replace compressor IPDU board 3
F15	Outdoor temperature sensor error. Detected at outdoor. Likely cause VRF equipment=Heat exchange (TE) sensor condition/location or Liquid line (TL) sensor condition/location, outdoor PCB fault Split equipment=Suction sensor (TS) condition/location Heat exchange sensor (TE) condition/location, outdoor PCB fault sensor value 20°c=12.5k ohms
F16	Pressure sensors miss-reading. Detected at outdoor. Likely cause incorrect characteristics of compressor discharge (Pd) & compressor suction (PS) pressure sensor or total loss of refrigerant
F22	Td3 sensor fault. Detected at outdoor. Likely cause compressor discharge sensor condition (Td3) or outdoor PCB fault sensor value 20°c=63k ohms
F23	Compressor suction pressure sensor fault. Detected at outdoor. Likely cause Suction transducer (PS) fault, outdoor PCB fault
F24	Compressor discharge pressure sensor fault. Detected at outdoor. Likely cause discharge transducer (Pd) fault, outdoor PCB fault
F29	Indoor PCB fault. Detected indoors. Likely cause replace indoor PCB
F31	Outdoor EEPROM Error. Detected at outdoor. Likely cause VRF equipment=power interruption, replace interface PCB Split equipment=replace condenser CDB board
H01	Excessive amps drawn by compressor. Detected at outdoor. Likely cause imbalance in voltage supplied from IPDU board to compressor, compressor lock / seizure. Retrieve sub-code for VRF from condenser to determine which compressor suffered failure 01=compressor1, 02=compressor2 & 03=compressor3. Retrieve fault sub-code from condenser interface PCB by placing rotary dials to position 1 / 1 / 1 for diagnosis.
H01 01	Excessive amps drawn by compressor 1. Detected at outdoor. Likely cause imbalance in voltage supplied to compressor 1 from inverter IPDU board 1, compressor 1 lock / seizure



Code	Fault Description
H01 02	Excessive amps drawn by compressor 2. Detected at outdoor. Likely cause imbalance in voltage supplied to compressor 2 from inverter IPDU board 2, compressor 2 lock / seizure
H01 03	Excessive amps drawn by compressor 3. Detected at outdoor. Likely cause imbalance in voltage supplied to compressor 3 from IPDU board 3, compressor 3 lock / seizure
H02	High amps drawn by compressor on start-up. Detected at outdoor. Likely cause imbalance in voltage supplied to compressor from IPDU board, compressor locked / seized. For VRF fault sub-code required to determine which compressor suffered failure 01=compressor1 02=compressor2 03=compressor3. Retrieve fault sub-code from condenser interface PCB by placing rotary dials to position 1 / 1 / 1 for diagnosis.
H02 01	High amps drawn by compressor 1 on start-up. Detected at outdoor. Likely cause imbalance in voltage supplied to compressor 1 from IPDU board 1, compressor 1 locked / seized
H02 02	High amps drawn by compressor 2 on start-up. Detected at outdoor. Likely cause imbalance in voltage supplied to compressor 2 from IPDU board 2, compressor 2 locked / seized
H02 03	High amps drawn by compressor 3 on start-up. Detected at outdoor. Likely cause imbalance in voltage supplied to compressor 3 from IPDU board 3, compressor 3 locked / seized
H03	Current detected in compressor off cycle. Detected at outdoor. Likely cause replace compressor IPDU board. For VRF fault sub-code required to determine which compressor suffered failure 01=compressor1 02=compressor2 03=compressor3. Retrieve fault sub-code from condenser interface PCB by placing rotary dials to position 1 / 1 / 1 for diagnosis.
H03 01	Current detected in compressor off cycle. Detected at outdoor. Likely cause replace compressor IPDU board 1
H03 02	Current detected in compressor off cycle. Detected at outdoor. Likely cause replace compressor IPDU board 2
H03 03	Current detected in compressor off cycle. Detected at outdoor. Likely cause replace compressor IPDU board 3
H04	Compressor 1 over-heat. Detected at outdoor. Likely cause compressor klixon activation, loss of refrigerant, poor refrigerant flow reducing cooling effect to compressor
H05	Compressor discharge temperature does not increase while compressor 1 operates. Detected at outdoor. Likely cause compressor discharge sensor (Td1) condition / location, outdoor PCB fault sensor value 20°c=63k ohms
H06	Low pressure protection operation. Detected at outdoor. Likely cause characteristics of suction pressure transducer (PS), system pump-down, interface PCB fault)
H07	Abnormal oil level / temperature alarm. Detected outdoor. Likely cause oil balance service valve, refrigerant loss, oil sensor condition (TK1 / TK2 / TK3 / TK4 / TK5), interface board PCB fault sensor value 20°c=63k ohms)
H08	TK Oil sensor fault. Detected at outdoor. Likely cause oil sensor condition, outdoor PCB fault. Fault sub code required to determine which sensor (TK1 / TK2 / TK3 / TK4 / TK5 sensor value 20°c=63k ohms). Retrieve fault sub-code from condenser interface PCB by placing rotary dials to position 1 / 1 / 1 for diagnosis.
H08 01	TK1 Oil sensor fault. Detected at outdoor. Likely cause oil sensor condition (TK1), outdoor PCB fault sensor value 20°c=63k ohms
H08 02	TK2 Oil sensor fault. Detected at outdoor. Likely cause oil sensor condition (TK2), outdoor PCB fault sensor value 20°c=63k ohms
H08 03	TK3 Oil sensor fault. Detected at outdoor. Likely cause oil sensor condition (TK3), outdoor PCB fault sensor value 20°c=63k ohms
H08 04	TK4 Oil sensor fault. Detected at outdoor. Likely cause oil sensor condition (TK4), outdoor PCB fault sensor value 20°c=63k ohms
H08 05	TK5 Oil sensor fault. Detected at outdoor. Likely cause oil sensor condition (TK5), outdoor PCB fault sensor value 20°c=63k ohms
H14	Compressor 2 over-heat. Detected at outdoor. Likely cause compressor klixon activation, loss of refrigerant, poor refrigerant flow reducing cooling effect to compressor



Code	Fault Description
H15	Compressor discharge temperature does not increase while compressor 2 operates. Detected at outdoor. Likely cause compressor discharge sensor
1115	(Td2) condition / location, outdoor PCB fault sensor value 20°c=63k ohms
H16	TK oil sensors do not detect temperature change while compressors operate. Detected at outdoor. Likely cause oil line (TK1 / TK2 / TK3 / TK4 / TK5) sensor condition / location, outdoor PCB fault sensor value 20°c=63k ohms. Retrieve fault sub-code from condenser interface PCB by placing rotary dials to position 1 / 1 / 1 for diagnosis.
H16 01	TK1 oil sensor does not detect temperature change while compressor 1 operates. Detected at outdoor. Likely cause oil line (TK1) sensor condition / location, outdoor PCB fault sensor value 20°c=63k ohms
H16 02	TK2 oil sensor does not detect temperature change while compressor 2 operates. Detected at outdoor. Likely cause oil line (TK2) sensor condition / location, outdoor PCB fault sensor value 20°c=63k ohms
H16 03	TK3 oil sensor does not detect temperature change while compressor 3 operates. Detected at outdoor. Likely cause oil line (TK3) sensor condition / location, outdoor PCB fault sensor value $20^{\circ}c=63k\Omega$
H16 04	TK4 oil sensor does not detect temperature change while compressors operate. Detected at outdoor. Likely cause oil line (TK4) sensor condition / location, outdoor PCB fault sensor value $20^{\circ}c=63k\Omega$
H16 05	TK5 oil sensor does not detect temperature change while compressors operate. Detected at outdoor. Likely cause oil line (TK5) sensor condition / location, outdoor PCB fault sensor value $20^{\circ}c=63k\Omega$
H25	Compressor discharge temperature does not increase while compressor 3 operates. Detected at outdoor. Likely cause compressor discharge sensor (Td3) condition / location, outdoor PCB fault sensor value 20°c=63k ohms
L03	Two or more lead units within group of indoor units. Detected indoors. Likely cause incorrect addressing, alteration in grouped set-up / wiring, requires re-addressing
L04	Duplicated outdoor line address. Detected at outdoor. Likely cause failure to correctly set line address before auto addressing
L05	Duplicated priority indoor unit, displayed on priority indoor unit. Detected indoors. Likely cause two units configured as priority units, correct configuration within engineer's menu 04
L06	Duplicated priority indoor unit, displayed on other than priority indoor unit. Detected indoors. Likely cause two units configured as priority units, correct configuration within engineering menu code 04
L07	Indoor unit group address incorrectly set. Detected indoors. Likely cause alteration of indoor group set-up, re-address required
L08	Indoor group / addresses unset. Detected at outdoor. Likely cause automatic addressing in-completed
L09	Indoor PCB capacity unset. Detected indoors. Likely cause failure to follow instruction accompanying new PCB
L10	Outdoor PCB capacity unset. Detected at outdoor. Likely cause failure to follow instructions accompanying new PCB
L17	Inconsistency of outdoor unit models. Detected at outdoor. Likely cause incorrect selection on outdoor model references
L18	Flow Selector unit error. Detected indoors. Likely cause indoor unit unable to heat on demand. Check power & communication to F/S Box from local indoor unit. Incorrectly configured indoor group sharing F/S box
L20	Duplicated central controller address. Detected indoors. Likely cause incorrectly set network address. Engineering code 03
L28	Quantity of outdoor units to high. Detected at outdoor. Likely cause to many outdoor units modularised together
L29	IPDU /PCB communication error. Detected at outdoor. Likely cause Split equipment=faulty or overheating inverter PCB. VRF equipment=loss in communication between condenser PCB's. Retrieve fault sub-code from condenser interface PCB by placing rotary dials to position 1 / 1 / 1 for diagnosis. Search fault code (without spaces) for diagnosis e.g. L2901



Code	Fault Description
L29 01	Compressor 1 IPDU board communication error. Detected at outdoor. Likely cause check communication cable linking all PCB's, replace Compressor 1 IPDU board
L29 02	Compressor 2 IPDU board communication error. Detected at outdoor. Likely cause check communication cable linking all PCB's, replace Compressor 2 IPDU board
L29 03	Compressor 1 & 2 IPDU board communication error. Detected at outdoor. Likely cause check communication cable linking all PCB's, replace Compressor 1 & 2 IPDU board
L29 04	Communication failure between PCB within condenser. Detected at outdoor. Fault Code is outdoor model series specific e.g. MMY-MAP###1HT8-E, MMY-AP###2HT8-E or MMY-MAP###4HT8-E therefore example fault code for L2904 will be (MMY-MAP0801HT8-E (series 1), MMY-MAP0802HT8-E (series 2), MMY-MAP0804HT8-E (series 4) search L29041, L29042 or L29044
L29 04 1	Fan IPDU board communication error. Detected at outdoor. Likely cause check communication cable linking all PCB's, replace fan IPDU board
L29 04 2	Fan IPDU board communication error. Detected at outdoor. Likely cause check communication cable linking all PCB's, replace fan IPDU board
L29 04 <mark>4</mark>	Compressor 3 IPDU board communication error. Detected at outdoor. Likely cause check communication cable linking all PCB's, replace Compressor 3 IPDU board
L29 05	Communication failure between PCB within condenser. Detected at outdoor. Fault Code is outdoor model series specific e.g. MMY-MAP###1HT8-E, MMY-AP###2HT8-E or MMY-MAP###4HT8-E therefore example fault code for L2905 will be (MMY-MAP0801HT8-E (series 1), MMY-MAP0802HT8-E (series 2), MMY-MAP0804HT8-E (series 4) search L29051, L29052 or L29054
L29 05 <mark>1</mark>	Compressor 1 IPDU & fan IPDU board communication error. Detected at outdoor. Likely cause check communication cable linking all PCB's, replace Compressor 1 IPDU & fan IPDU board
L29 05 <mark>2</mark>	Compressor 1 IPDU & fan IPDU board communication error. Detected at outdoor. Likely cause check communication cable linking all PCB's, replace Compressor 1 IPDU & fan IPDU board
L29 05 <mark>4</mark>	Compressor 1 & 3 IPDU board communication error. Detected at outdoor. Likely cause check communication cable linking all PCB's, replace Compressor 1 & 3 IPDU board
L29 06	Communication failure between PCB within condenser. Detected at outdoor. Fault Code is outdoor model series specific e.g. MMY-MAP###1HT8-E, MMY-AP###2HT8-E or MMY-MAP###4HT8-E therefore example fault code for L2906 will be (MMY-MAP0801HT8-E (series 1), MMY-MAP0802HT8-E (series 2), MMY-MAP0804HT8-E (series 4) search L29061, L29062 or L29064
L29 06 <mark>1</mark>	Compressor 2 IPDU & fan IPDU board communication error. Detected at outdoor. Likely cause check communication cable linking all PCB's, replace Compressor 2 IPDU & fan IPDU board
L29 06 <mark>2</mark>	Compressor 2 IPDU & fan IPDU board communication error. Detected at outdoor. Likely cause check communication cable linking all PCB's, replace Compressor 2 IPDU & fan IPDU board
L29 06 <mark>4</mark>	Compressor 2 & 3 IPDU board communication error. Detected at outdoor. Likely cause check communication cable linking all PCB's, replace Compressor 2 & 3 IPDU board
L29 07	Communication failure between PCB within condenser. Detected at outdoor. Fault Code is outdoor model series specific e.g. MMY-MAP###1HT8-E, MMY-AP###2HT8-E or MMY-MAP###4HT8-E therefore example fault code for L2907 will be (MMY-MAP0801HT8-E (series 1), MMY-MAP0802HT8-E
L29 07 <mark>1</mark>	(series 2), MMY-MAP0804HT8-E (series 4) search L29071, L29072 or L29074 for diagnosis Communication error between PCB within condenser. Detected at outdoor. Likely cause check communication cable linking all PCB's, phase missing on power supply, replace interface PCB



Code	Fault Description
L29 07 <mark>2</mark>	Communication error between PCB within condenser. Detected at outdoor. Likely cause check communication cable linking all PCB's, phase missing on
	power supply, replace interface PCB
L29 07 <mark>4</mark>	Compressor 1, 2 & 3 IPDU board communication error. Detected at outdoor. Likely cause check communication cable linking all PCB's, replace
	Compressor 1, 2 & 3 IPDU board
L29 08	Fan IPDU board communication error. Detected at outdoor. Likely cause check communication cable linking all PCB's, replace fan IPDU board
L29 09	Compressor 1 IPDU & fan IPDU board communication error. Detected at outdoor. Likely cause check communication cable linking all PCB's, replace
	Compressor 1 IPDU & fan IPDU board
L29 0A	Compressor 2 IPDU & fan IPDU board communication error. Detected at outdoor. Likely cause check communication cable linking all PCB's, replace
	Compressor 2 IPDU & fan IPDU board
L29 0B	Compressor 1 & 2 IPDU board & fan IPDU board communication error. Detected at outdoor. Likely cause check communication cable linking all PCB's,
	replace Compressor 1 & 2 IPDU PCB & fan IPDU board
L29 0C	Compressor 3 IPDU board & fan IPDU board communication error. Detected at outdoor. Likely cause check communication cable linking all PCB's,
229 00	replace Compressor 3 IPDU board & fan IPDU board
L29 0d	Compressor 1 & 3 IPDU board & fan IPDU board communication error. Detected at outdoor. Likely cause check communication cable linking all PCB's,
225 00	replace Compressor 1 & 3 IPDU board & fan IPDU board
L29 0E	Compressor 2 & 3 IPDU board & fan IPDU board communication error. Detected at outdoor. Likely cause check communication cable linking all PCB's,
225 02	replace Compressor 2 & 3 IPDU PCB & fan IPDU board
L29 0F	Communication error between PCB within condenser. Detected at outdoor. Likely cause check communication cable linking all PCB's, phase missing on
	power supply, replace interface PCB
L30	Auxiliary interlock in indoor unit. Detected indoors. Likely cause external interlock in CN80 socket on indoor unit
P01	Indoor fan motor error. Detected indoors. Likely cause indoor fan motor or wiring to motor
P03	High compressor discharge temperature. Detected at outdoor. by TD1 @ 115°c. Likely cause low refrigerant, poor refrigerant flow and airflows & TD1
	sensor condition sensor value 20°c=63k ohms
	High pressure switch activation. Detected at outdoor. Likely cause poor airflows over indoor / out dependant on operation, restriction in refrigerant
P04	flow, non-condensable mixed with refrigerant. Fault sub code required to determine which H.P. Switch activated 01=compressor 1 02=compressor 2
	03=compressor 3. Retrieve fault sub-code from condenser interface PCB by placing rotary dials to position 1 / 1 / 1 for diagnosis.
P04 01	Compressor 1 high pressure switch activation. Detected at outdoor. Likely cause poor airflows over indoor / out dependant on operation, restriction in
	refrigerant flow, non-condensable mixed with refrigerant
P04 02	Compressor 2 high pressure switch activation. Detected at outdoor. Likely cause poor airflows over indoor / out dependant on operation, restriction in
	refrigerant flow, non-condensable mixed with refrigerant
P04 03	Compressor 3 high pressure switch activation. Detected at outdoor. Likely cause poor airflows over indoor / out dependant on operation, restriction in
	refrigerant flow, non-condensable mixed with refrigerant
P05	Phase-missing detection / phase order error, compressor inverter High Voltage. Retrieve fault sub-code from condenser interface PCB by placing rotary
	dials to position 1 / 1 / 1 for diagnosis. Search fault code (without spaces) for diagnosis e.g. P0501
P05 00	Phase-order incorrect or phase missing. Detected at outdoor. Likely cause issue with power supply to condenser, or phase order wrong, swap L2 & L3



Code	Fault Description
P05 01	Phase-missing detection (series 1 & 2) or High D.C. inverter voltage (series 4). Detected at outdoor. Fault Code is outdoor model series specific e.g. MMY-MAP###1HT8-E, MMY-AP###2HT8-E or MMY-MAP###4HT8-E therefore example fault code for P0501 will be (MMY-MAP0801HT8-E (series 1), MMY-MAP0802HT8-E (series 2), MMY-MAP0804HT8-E (series 4) search P05011, P05012 or P05014
P05 01 1	Phase-missing detection. Detected at outdoor. Likely cause error on power supply to condenser
P05 01 2	Phase-missing detection. Detected at outdoor. Likely cause error on power supply to condenser
P05 01 4	High D.C. inverter voltage. Detected at outdoor. Likely cause compressor 1 IPDU board overheat or failure
P05 02	Phase-order incorrect (series 1 & 2) or High D.C. inverter voltage (series 4). Detected at outdoor. Fault Code is outdoor model series specific e.g. MMY-MAP###1HT8-E, MMY-AP###2HT8-E or MMY-MAP###4HT8-E therefore example fault code for P0502 will be (MMY-MAP0801HT8-E (series 1), MMY-MAP0802HT8-E (series 2), MMY-MAP0804HT8-E (series 4) search P05011, P05012 or P05014
P05 02 <mark>1</mark>	Phase-order incorrect. Detected at outdoor. Likely cause issue with power supply to condenser, swap L2 & L3 to correct
P05 02 <mark>2</mark>	Phase-order incorrect. Detected at outdoor. Likely cause issue with power supply to condenser, swap L2 & L3 to correct
P05 02 <mark>4</mark>	High D.C. inverter voltage. Detected at outdoor. Likely cause compressor 2 IPDU board overheat or failure
P05 03	High D.C. inverter voltage. Detected at outdoor. Likely cause compressor 3 IPDU board overheat or failure
P07	Overheating compressor IPDU / inverter board. Detected at outdoor. Likely cause poorly secured inverter PCB to heat-sink, faulty IPDU. Fault sub code required to determine which IPDU overheated 01=IPDU1 02=IPDU2 03=IPDU3. Retrieve fault sub-code from condenser interface PCB by placing rotary dials to position 1 / 1 / 1 for diagnosis.
P07 01	Overheating compressor 1 IPDU / inverter board. Detected at outdoor. Likely cause poorly secured inverter PCB to heat-sink, faulty IPDU board 1
P07 02	Overheating compressor 2 IPDU / inverter board. Detected at outdoor. Likely cause poorly secured inverter PCB to heat-sink, faulty IPDU board 2
P07 03	Overheating compressor 3 IPDU / inverter board. Detected at outdoor. Likely cause poorly secured inverter PCB to heat-sink, faulty IPDU board 3
P10	Indoor float switch open circuit as result of high condensation levels within drip tray, detected indoors. Likely cause faulty float switch, faulty lift pump, debris blocking drain
P12	Indoor fan motor trouble. Detected indoors. Likely cause fan motor locked, incorrectly configured PCB, indoor PCB fault
P13	Outdoor liquid back detection in condenser while in OFF cycle. Detected at outdoor. Likely cause increase in pressure within dormant condenser, possible PMV valves passing
P15	High compressor suction or discharge temperature. Detected at outdoor. Likely cause sensor condition (TS1 or TD1, 2 or 3), interface PCB fault, loss of refrigerant TS1 sensor value $20^{\circ}c=12.5k$ ohms TD1,2 & 3 sensor value $20^{\circ}c=63k$ ohms. Retrieve fault sub-code from condenser interface PCB by placing rotary dials to position $1 / 1 / 1$ for diagnosis.
P15 01	High compressor suction temperature. Detected at outdoor. Likely cause suction sensor condition (TS1), interface PCB fault, loss of refrigerant sensor value 20°c=12.5k ohms
P15 02	High compressor discharge temperature. Detected at outdoor. Likely cause discharge sensor condition (TD1, TD2 or TD3), interface PCB fault, loss of refrigerant sensor value 20°c=63k ohms
P17	High compressor discharge temperature. Detected at outdoor. by TD2 @ 115°c. Likely cause low refrigerant, poor refrigerant flow and airflows & TD2 sensor condition sensor value 20°c=63k ohms
P18	High compressor discharge temperature. Detected at outdoor. by TD3 @ 115°c. Likely cause low refrigerant, poor refrigerant flow and airflows & TD3 sensor condition sensor value 20°c=63k ohms
P19	Incorrect temperature / pressure reading at condenser. Detected at outdoor. Likely cause check characteristics of pressure transducers (PS & Pd) and temperature sensors (TS1, TE1 & TL), interface PCB fault sensor value 20°c=12.5k ohms



Code	Fault Description
P20	High pressure protection detected by discharge pressure transducer reading @ 36bar. Detected at outdoor. Likely cause characteristics of discharge
P20	pressure transducer (Pd), interface PCB, poor airflows across condensers
	Outdoor fan motor error. Detected at outdoor. Likely cause Split equipment, locked / faulty fan motor, faulty PCB VRF Equipment. Retrieve fault sub-
P22	code from condenser interface PCB by placing rotary dials to position 1 / 1 / 1 for diagnosis. Search fault code (without spaces) for diagnosis. e.g.
P22 03	Outdoor fan motor error. Detected at outdoor. Likely cause locked / faulty fan motor, faulty fan IPDU PCB. Fan motor has 3 ohms resistance on any 2
	wires Outdoor fan motor error. Detected at outdoor. Likely cause locked / faulty fan motor, faulty fan IPDU PCB. Fan motor has 3 ohms resistance on any 2
P22 34	wires
	Outdoor fan motor error. Detected at outdoor. Likely cause locked / faulty fan motor, faulty fan IPDU PCB. Fan motor has 3 ohms resistance on any 2
P22 37	wires
P22 E1	Fan IPDU board error. Detected at outdoor. Likely cause error on DC supply voltage to fan IPDU PCB or problem with mains voltage onto condenser
P22 E2	Fan IPDU board error. Detected at outdoor. Likely cause error on DC supply voltage to fan IPDU PCB or problem with mains voltage onto condenser
P22 E3	Fan IPDU board error. Detected at outdoor. Likely cause error on DC supply voltage to fan IPDU PCB or problem with mains voltage onto condenser
P26	Compressor IPDU PCB Short circuit. Detected at outdoor. Likely cause electrical fault on compressor, faulty compressor inverter board. Before replacing
F20	PCB prove compressor is good. Retrieve fault sub-code from condenser interface PCB by placing rotary dials to position 1 / 1 / 1 for diagnosis.
P26 01	Compressor 1 IPDU PCB Short circuit. Detected at outdoor. Likely cause electrical fault on compressor 1, faulty compressor 1 inverter board. Before
12001	replacing PCB prove compressor is good
P26 02	Compressor 2 IPDU PCB Short circuit. Detected at outdoor. Likely cause electrical fault on compressor 2, faulty compressor 2 inverter board. Before
	replacing PCB prove compressor is good
P26 03	Compressor 3 IPDU PCB Short circuit. Detected at outdoor. Likely cause electrical fault on compressor 3, faulty compressor 3 inverter board. Before
	replacing PCB prove compressor is good
P29	Compressor position detection error. Detected at outdoor. Likely cause fault on compressor, faulty compressor inverter board. Before replacing inverter PCB prove compressor is good. Retrieve fault sub-code from condenser interface PCB by placing rotary dials to position 1 / 1 / 1 for diagnosis.
	Compressor 1 position detection error. Detected at outdoor. Likely cause fault on compressor 1, faulty compressor 1 inverter board. Before replacing
P29 01	inverter PCB prove compressor is good
	Compressor 2 position detection error. Detected at outdoor. Likely cause fault on compressor 2, faulty compressor 2 inverter board. Before replacing
P29 02	inverter PCB prove compressor is good
	Compressor 3 position detection error. Detected at outdoor. Likely cause fault on compressor 3, faulty compressor 3 inverter board. Before replacing
P29 03	inverter PCB prove compressor is good
<b>D</b> 20	Indoor unit other than lead indoor suffering fault. Detected on central controller. Likely cause to diagnose retrieve fault code from local remote
P30	controller to indoor group
P31	Indoor unit other than lead indoor suffering fault. Detected indoors. Likely cause to diagnose retrieve fault code from local remote controller to indoor
FJI	group



### Error Detected by - TCC-Link Central Controller

	Check Code		١	Vireless	Remo	e				
Central		Outdoor 7 Segment Display	egment Display					Check Code Name	Judging Device	
Control Device		Auxiliary Code	Dele AI Central Controller O T R			F				
C05					-			Sending error in TCC-Link central control device	TCC-LINK	
C06					-			Receiving error in TCC-Link central control device	TCC-LINK	
C12					-			Batch alarm of general purpose equipment control interface	HA control interface I/F	
P30		Differs according to error conte	nts of unit with occurre	ence of a	alarm			Group control follower unit error		
r JU			(L20	) is displ	ayed)			Duplicated central control addresses	TCC-LINK	

		Black Pear Error C	ode Cross Re	eference.	
Black Pear	Toshiba	Description	Black Pear	Toshiba	Description
Error Code	Error Code		Error Code	Error Code	
1005	C05	Sending error in TCC-Link central control device	3001	F01	Indoor TCCJ sensor error
1006	C06	Receiving error in TCC-Link central control device	3002	F02	Indoor TC2 sensor error
1012	C12	Batch alarm of general purpose equipment control interface	3003	F03	Indoor TC1 sensor error
2001	E01	Communication error between indoor and remote controller (Detected at	3004	F04	TD1 sensor error
2001		remote controller side)			
2003	E03	Communication error between indoor and remote controller (Detected at	3005	F05	TD2 sensor error
2005	105	indoor side)	3006	F06	TE1 sensor error
2004	E04	Communication circuit error between indoor / outdoor (Detected at indoor	3007	F07	TL sensor error
2004	204	side)	3008	F08	TO sensor error
2006	E06	Decrease of number of indoor units.	3010	F10	TA sensor error
2007	E07	Communication circuit error between indoor / outdoor (Detected at outdoor side)	3012	F12	TS1 sensor error
2008	E08	Duplicated indoor addresses	3013	F13	TH sensor error
2009	E09	Duplicated master remote controllers	3015	F15	Outdoor temperature sensor misconnection (TE1-TL)
2010	E10	Communication error between indoor Boards	3016	F16	Outdoor pressure sensor misconnection (Pd – Ps)
2012	E12	Automatic address start error	3023	F23	Ps sensor error
2015	E15	No indoor automatic address	3024	F24	Pd sensor error
2016	E16	Over capacity / Number of connected indoor units	3029	F29	Indoor other error
2018	E18	Communication error between indoor header and follower units.	3031	F31	Outdoor EEPROM error
2019	E19	Outdoor header unit's quantity error	4001	H01	Compressor break down
2020	E20	Other line connected during automatic address	4002	H02	Magnetic switch error / Overcurrent relay operation / Compressor error (lock)
2023	E23	Sending error in communication between outdoor units	4003	H03	Current detection circuit error
2025	E25	Duplicated follower outdoor address	4004	H04	Compressor 1 case thermal operation
2026	E26	Decrease of number of connected outdoor units	4006	H06	Low pressure protection operation
2028	E28	Follower outdoor unit error	4007	H07	Low oil level protection
2031	E31	IPDU Communication error	4008	H08	Oil level temperature sensor error
			4014	H14	Compressor 2 case thermal operation
			4016	H16	Oil level detection circuit error / Magnetic switch error / Overcurrent relay error



		Black Pear Error Co	ode Cross Refe	rence.	
Black Pear	Toshiba	Description	Black Pear	Toshiba	Description
Error Code	Error Code		Error Code	Error Code	
6003	L03	Duplicated indoor header units	7001	P01	Indoor fan motor error
6004	L04	Duplicated outdoor line address	7003	P03	Discharge temperature TD1 error
6005	L05	Duplicated indoor units with priority	7004	P04	High-pressure switch detection error
6005	LUS	(Displayed in indoor unit with priority)	7005	P05	Phase-missing detection / Phase order error
6006	L06	Duplicated indoor units with priority	7007	P07	Heat sink overheat error
6006	108	(Displayed in unit other than indoor unity with priority)	7010	P10	Indoor overflow error
6007	L07	Group line in individual indoor unit	7012	P12	Indoor fan motor error
6008	L08	Indoor group/Address unset	7013	P13	Outdoor liquid back detection error
6009	L09	Indoor capacity unset	7015	P15	Gas leak detection
6010	L10	Outdoor capacity unset	7017	P17	Discharge temperature TD2 error
6020	L20	Duplicated central control addresses	7019	P19	4-way valve inverse error
6028	L28	Maximum number of outdoor units exceeded	7020	P20	High pressure inverse error
6029	L29	Number of IPDU's error	7022	P22	Outdoor fan IPDU error
6030	L30	Auxiliary interlock in indoor unit	7026	P26	Giant Transistor short circuit protection error
6031	L31	IC error	7029	7031	Compressor position detection circuit error
			7030	P30	Follower indoor unit error (Group error)
Special B	lack Pear		7031	P31	Follower indoor unit error (Group error)
Error	Codes				
69	99	Unit does not exist on the system			
80	00	No error detected			
25	55	No error detected.			



## **TCC-net Local Hard Wired Controller Guidelines**

**RAV & VRF** 







**RBC-ASC11E** 



RBC-AMS41-E



### RBC-AMS54/55E-ES



RBC-AMT32-E



**RBC-AMS51E** 



### **System Configuration Menu**

Hard wired remote controllers which allow access to the configuration menu are: RBC-ASC11-E, RBC-AMT32-E, RBC-AMS41-E, RBC-AMS51E, RBC-AMS54/55E-ES.

RBC-AS41E, Infra-Red Remotes and Central Controllers Cannot be utilised for setting configuration items.

A number of items are configurable by a wired controller – if an indoor unit without a wired controller requires configuration, a wired remote can be temporarily connected for the procedure to be undertaken. In order to access the men**U**.

- The indoor units to be configured will be chosen by pressing the UNIT button.
- The indoor unit being configured runs its fan and swings its louvers (if possible).
- Use SET TEMPERATURE up/down buttons to scroll through the configurable items Use TIMER up/down buttons to choose the configuration value for Use
- SET to confirm configuration value Use CL to undo an incorrect setting provided that configurable item has not been changed)
- Use CHECK to return to normal operation.

#### **EXAMPLES** of COMMON CONFIGURABLE OPTIONS

ITEM	DESCRIPTION		VALUE	DEFAULT									
01	Filter alarm time	Filter sign displayed after selected time has elapsed – or by external pressure switch (CN70)	0000: Inactive 0001: 150 H 0002: 250 H 0004: 1000 H 0003: 500 H 0005: External switch	0002									
02	Dirty environment	Allows filter alarm time to be halved if used in a dirty environment	0000: Standard 0001: Dirty	0000									
03	Network address	When under network control.	0099: Unset 0001 to 0064 available	0099									
04	Priority Setting for Remote Controller	0 = Normal 1= Priority (This remote has priority of mode setting	0000 = Standard 0001 = Priority	0000									
06	Stratification control	Increases effective return air temperature setting in heating mode (0 to 10K)	0000 to 0010	0002; +2 <sup>o</sup> C Floor type 0000; 0°C									
0C	Preheat	Preheat indication on display 0000 = available 0001 = unavailable											
0d	Auto mode	Enable or disable Auto mode	0000 = available 0001 = unavailable	0000 except SMMSe									
0E	SHRMi only	Used when multiple indoor units are served via a single FS box	0000 = normal 0001= multiple units	0000									
0F	Heat Mode	Enable or disable Heat Mode	0000 = available 0001 = unavailable	0000									
10	Indoor unit model	Must be set when replacing indoor printed circuit board	0000: 1-way cassette (s models)       0001: 4-way cassette       0002: 2-way cassette       0003: 1-way cassette (y models)       0004: duct (standard)       0005: slim duct       0006: duct (high static)       0007: ceiling       0008: hi wall       0010: console       0011: concealed floor       0011: concealed floor       0013: tall cabinet       0016: fresh air intake       0050: air to air heat exchanger										
11	Indoor unit capacity	0000 will generate a (L09) fault	$\begin{array}{c ccccccccccccccccccccccccccccccccccc$										
12	System number	value may be set manually but it must be done via the wired controller – on an individual basis. Settings are 0001 to 0030	0001: outdoor unit 1 0002: outdoor unit 2	0099									
13	Indoor unit number	Indoor units connected to a common outdoor unit (e.g. twinned indoor units) will have the same system number - settings are 0001 to 0064. Automatically allocated – but may be manually overridden.	0001: indoor unit 1 0002: indoor unit 2	0099									
14	Group master/slave	Allows selection of master indoor unit within group. Automatically allocated but may be manually overridden.	0000: single indoor unit 0001: group master 0002: group slave	0099									
15	Temperature Sensor	Compensation for missing temperature sensor (split systems ONLY) other settings produce F03 fault code	0022	0022									



ITEM	DESCRIPTION													VALI	UE	DEFAUL	.т	
16	Indoor Fan				In	door far	n speed	selection	n. Bin	ary add	ition.				= all speeds available uto; 2 = low; 4 = medium; 8 = high	0015 except hi 0008	gh static	
17	Set point shift			Co	ooling	tempera	ature se	et point sl	nift. (s	hifted b	y 1 to 10	k)			) = no shift, 0001 = 1 k shift, - ) = 10 k shift	0000		
19	Louver functions			I	None,	swing o	nly, swi	ing and a	iuto (v	vhere a	pplicable	)			: disabled 0001: swing only : all options			
1b	Compressor on time			Compres	sor mi	nimum o	on time		(0 =	= 5 minu	utes 1 = 4	4 minute	es)	0000:	: 0 – 5 min 0001: 1 - 4 min.	0000		
1E	Dead band - auto			Changeo	ver se	ensitivity	in auto	matic mo	ode.	(1 t	to 10 k a	djustable	e)	0000:	: 0 K 0010: 10 K	0003		
1F	Max. Setting			Co	oling	mode m	aximun	n temper	ature	setting	(18 – 29 <sup>d</sup>	°C)		0018	= 18°C 0020 = 20°C 0029 = 29°C	29 ° C		
20	Min. Setting			Co	oling	mode m	ninimum	n tempera	ature	setting (	(18 – 29°	C)		0018	= 18°C 0020 = 20°C 0029 = 29°C	18 ° C		
21	Max. Setting			He	ating	mode m	aximun	n temper	ature	setting	(18 – 29°	°C)		0018	= 18°C 0020 = 20°C 0029 = 29°C	29 ° C		
22	Min. Setting			He	eating	mode m	ninimum	tempera	ature	setting (	(18 – 29°	C)		0018	= 18°C 0020 = 20°C 0029 = 29°C	18 º C		
23	Max. Setting			[	Dry mo	ode max	kimum t	emperati	ure se	etting (18	8 – 29°C	)		0018	= 18°C 0020 = 20°C 0029 = 29°C	29 ° C		
24	Min. Setting				Dry m	ode min	imum t	emperati	ire se	tting (18	3 – 29°C)	)		0018	= 18°C 0020 = 20°C 0029 = 29°C	18 ° C		
25	Max. Setting			A	uto m	ode ma	ximum	temperat	ure se	etting (1	8 – 29°C	;)		0018	= 18°C 0020 = 20°C 0029 = 29°C	29 ° C		
26	Min. Setting			A	Auto m	iode mir	nimum 1	emperat	ure se	etting (1	8 – 29°C	)		0018	= 18°C 0020 = 20°C 0029 = 29°C	18 ° C		
28	Auto restart						Ena	ble or dis	able					0000:	: disabled 0001: enabled	0000		
29	Humidifier condition					Ope	rating c	ondition	of hur	nidifier				0000	: Usual 0001: Condition ignore	0000		
2A	CN70					Selectio	on of op	tional eri	or inp	out (CN7	70)				): Filter input : Alarm input 0002: None	0002		
2d	Modes available					Binar	y additi	on of mo	des a	vailable	-				i= all modes an; 2 = cool; 4 = dry 8 = heat	0015		
2E	External On / Off control				hing o	ption, re	emove j	1 and 2 umper 0 ink 01 in	l mas	ter indo	or PCB a	allows	al	stops	) = group starts when made s when open 0001 = enable n made, disable when open	0000		
31	External fan control		Use	d for setti				ntroller ar or VN-M				n A/C sy	stems	0000	e disable 0001 = enabled	0000		
32	Sensor location				Re	turn air/	ontrol for VN-M units when paired with A/C systems /room sensor OR in local controller								): return air sensor 0001: remote sensor	0000		
33	Unit of temperature						Celsius or Fahrenheit								= Celsius 0001 = Fahrenhe	t 0000		
36	Remote controller						Temperature display								: temperature setting : temperature room sensing	0000		
40	Drain pump						Drain pump control								): None 0001: Pump ON 2: None 0003: Pump OFF	0003		
45	Anti-smudge			2	l-way	cassette	e anti sr	nudge el	fect v	ia louve	r positio	n			enabled 0001 = disabled	0000		
	1-Way Cassette Airflow Correction						AP015, 018         AP024           3.5         3.8							0000		0000		
	Ceiling height (m)							4.0 4.2				4.0 4.2		0001 0003				
	2-Way Cassette						AF	2.7	P030	)	AP36	6 to APC 2.7	)56	0000	1			
	Airflow correction Ceiling height (m)							3.2				3.0		0001		0000		
						RAV56	*	3.8	AV80	)*	RA	3.5 AV110*-	160*	0003	5			
	4-Way Cassette	AP		to AP012		015 to /		AP02	4 to A	P030		036 to A						
	Airflow correction Ceiling height (m)	4-way 2.7	3-w	ay 2-way 8 3.0	4-way 2.8	y 3-way 3.2	2-way 3.5	4-way 3.0	3-way 3.3	2-way 3.6	4-way 3.9	3-way 4.2	2-way 4.5	0000				
		-	-	-	3.2	3.5	3.8	3.3	3.5	3.8	4.2	4.4	4.6	0001		0000		
		-	-		3.5	3.8	- RA\	3.6 / <b>40</b> *	3.8	-	4.5 RA	4.6 <b>V56</b> *	-	0003				
	4-Way Compact Cassette	4	<b>\P0</b>	07 to APC	12		AP	015			AF	P018			-			
	Airflow correction			2.7		-	2.					3.2		0000		0000		
5d	Ceiling height (m)			-		-	3.					3.4 3.5		0002				
				-			RAV4	0*-56*				•						
	Slim Ducted							o AP018	4		AP0244 1		74		7			
	Airflow correction External static			10 Pa				Pa				) Pa		0000	)	0000		
	pressure			20 Pa 35 Pa				Pa Pa				) Pa 5 Pa		0001	3			
		50 Pa					50	Pa				) Pa		0006	6			
		RAV40*-56*					RA\					0*-160*						
		-	AP007 to AP018 A 30 Pa					o AP030			AP036		i8		1	RAV40*	0001	
	Standard Ducted		40 Pa					Pa Pa				) Pa ) Pa		0001		RAV-80* RAV110*	0001 0003	
	Airflow correction External static		50 Pa					Pa				) Pa		0000		RAV110 RAV140*		
	pressure	65 Pa					65 Pa 65 Pa (							0002		RAV160*		
			_	80 Pa		<u> </u>		Pa				) Pa		0004		AP007-018 000		
				100 Pa		──		Pa				0 Pa		0005		AP024-0		
	L			120 Pa			120	Pa			12	0 Pa		0006		AP036-0	58 0003	



ITEM	DESCRIPTION	VALUE	DEFAULT										
60	Timer lock	Locks timer in wired local controller – maintaining last setting 0000: unlocked 0001: locked	0000										
62	Anti-smudge	4-way cassette – ant smudge via fan speed (Coanda effect)	0001										
69	Louver	Louver restriction when cooling 0000 = restricted to horizontal positions 0001 = full range of movement	0000										
6E	Setting for air direction kit (1)	GM56         GM10         GM140           Standard         0000         <											
77	Dual set point	RBC - AMS54/55E - ES ONLY 0000 = Available 0001 = Unavailable 0											
88	Setting for air direction kit (2)	GM56         GM80         GM140           Standard         0000         0072         0075         0070           3-way air flow         0060         0060         0048         ca           2-way air flow         0050         0050         0048         ca											
8b	Heating Correction	Heating output reduction split systems only 0000: None 0001: Correction	0000										
8C	Forced Defrost	Run group in HEAT mode after setting defrost is conducted automatically.         0000 = disabled           Value is reset automatically back to 0000         0001 = enabled	0000										
AO	Fan & Pump	Fan and pump operation during oil retrieval mode (VRF cassettes ONLY) 0000 = fan off, pump on 0003 = fan on, pump on	0003										
b3	Soft Cooling	RBC-AMS54/55E-ES 0000 = Unavailable 0001 – Available 00											
b5	Occupancy Sensor	Where applicable 0000 = None 0001 = Occupancy sensor provided 00											
b6	Occupancy sensor	Enable / Invalid.         Absence time judgement time.         0000 = Invalid.         0001 = 30min.           0002 = 60min.         0004 = 120min.         0005 = 150min.	0002										
b7	Occupancy sensor	Operation at absent time. 0000 = Standby 0001 = Operation stop	0000										
C2	Energy save	Outdoor unit energy demand 1% increments 50 to 100% 0050 ~ 0100	0075										
CE	Replace indoor PCB	4-Way cassette unit capacity code         0000 = disable           0009: = RAV40*         0009: = RAV56*           00112: = RAV80*         0015: = RAV10*           0015: = RAV10*         0017: = RAV10*           0017: = RAV10*         0018: = RAV10*	0000										
d0	Power Saving Mode	Whether the power saving mode can be set by the remote controller 0000 = Invalid 0001 = Valid	0001										
d3	Self-clean operation	Self-clean dry operation         0000 = disable         0001 = enable           Operative Operation         0000 = A shared         0004 = D shared	0001										
E6 F0	Wireless Channel Swing mode	Compact Cassette. Channel selection         0000 = A channel         0001 = B channel           Compact Cassette. Louver swing options         0001 = Standard         0002 = Dual swing	0000										
F1	Louvre lock Flap 1	Compact Cassette. Louver swing options     0003 = Cycle swing     0       0000 Full swing     0000 Full swing       0000 Fill swing											
F2	Louvre lock Flap 2	0002 Fixed position 2	1										
F3	Louvre lock Flap 3	4-Way cassette 5 fixed positions 0003 Fixed position 3	0000										
F4	Louvre lock Flap 4	0004 Fixed position 4	-										
		0005 Fixed position 5 (Downward Discharge)	)										
F6	Application control kit	Presence of Application Control Kit (TCB-PCUC1/2E-1) 0000 = None 0001 = Exist 000											

Note: Some options are model specific.



			N-1	зщÈ	1	Чe¥	tev;		HPC.	Ì.		100			=.0	649	#		DV6	=:	:	19	1.341	008	eg.	6	0	-	
								-1		1				agenters 1				mana Mi				Carlos T						ek.	_
Accession Parts List		THE REAL PROPERTY OF A DESCRIPTION OF A	ENV/CMS01011	PURING WORKS	PANDARADANA	AAVAMMUTE &	# ALL POINTER AVA	TATUTO INTRACTOR	- Biall/Ide1WoliANOK	IL COLLEGE SOCIETY OF THE PARTY	#INVERVERVERVER	3-10-10-10-10-10-10-10-10-10-10-10-10-10-	International and the second s	PAURINO(MENA	RAVE MANAGER	Revense historie	WAVEFARE STREET	\$40,804561819-2	association and a second secon	Advance (digine)	ANVARATED TO A	PAIDING MEANS	SALVANA AND	RAVEMINDICIPAL	RAN-PART HOTOTHYE	WAN OPANIATES.	HAWGPECTANK H	STATILITICS.	WAY CHIRDLOCK
	NIC-ANGLE-ENIE			ŝ.					-	t	-																		
	RECIMINATED CEL			×			1			t					- 0					0		-08						1	
West 2 Remain Counses	HIC-MARE									E					-							1 (Mar)							
	ARC ADDITION									T	8		1.00				1												
	[BIG664]	01				10			t					-0					0		-04								
	R CAXImple	_																		5			h		łΞ.				
	ACTINA INT									1	-													1					
Winness Remains	TOP-AXORE :			C		1				Ē					÷Þ					C .									
SOUTHER .	+ the offe			1						Г					1										1				
	REAKER	_								L												100							
Schedule Think	CROBER LINE			×.	-					T			-		1.					C .									
TOTAL PROPERTY AND INCOME.	TURCHINE -	-								t.		τ.			11			-		۰.			CT.	τ		1			
	and pulled when									Г																			
CelligRowt	(REC-00/21FG205E)			1	1.0					Ī		κ.												1					
	-RIC-USIT-PTWER	_								1								1										-	
Occupation (Contraction)	Southing:		E		1					1		۰.										-			IE			8	
Occupior Series	1103b-5884315-81		1	х.						Г	T							1						I	1				
Antor Martineor	THEOREM									Ī.								1						1					
COMPANY AND ITTACTA	308-04-CEALOR																												
families for ferrard	206-SP350208			κ.			1			Г																			
All states	TOD ST HOSE		1	1											11														-
ALCONOMIC IN CONTRACTOR	TOHOLESIE		_	۰.		-7				÷																			
We describe the set of the	At the top of the time at 100-00 the top of						R																	1					
Average Number of Party	TOP THREE .			4				1				2												1					
Ophini Converting \$3.1	20640000							-																	_				
	NOR-RELICITIES			Ī						II								15		. )]				11					
seast inconstitionors;	TOP-STREE-HIPE									T									D.					i'	1	I			
	2530100100						-															-							
Accellacteria.	ICONTO 10			Ī						Ū														U.	I				



Cassette PCB

⇔

⇔

⇔

⇔

### **TCC-Net Control**

### Features


- ⇔ 2 wire, screened, non-polarised controller connection
- ⇔ Infrared control available for cassette, under ceiling, high wall, ducted models
- Remote temperature sensing available, Unit, Wired controller, Separate room sensor ⇔
- Automatic addressing of groups and twins ⇔
- Optional control of external fan, (RBC-SMF1) ⇔
- ⇔ High ceiling compensation (code 5d)
- ⇔ Time for filter warning is configurable (code 01)
- ⇔ Each mode of operation (auto - heat - cool - dry) may have a different temperature set point
- ⇔ Auto restart is configurable (code 28)

DC fan motor with feedback circuit


and PCB activity when illuminated.

Wired or infrared control (or both)

Drain pump and float switch



### Wired controller (RBC-AMT32/41)




- Mode of operation 1
- 2. Louver
- Fixed louver 3.
- Filter 4. 5.
- Not used 6. Self-clean function
- Defrosting 7.
- 8. Ready
- 9. Heating ready
- 10. Not used
- 11. Frost protection 12.
  - Numeric display
  - Remote controller sensor Not used
- 14. Set Temperature
- 16. Central control
- 17. Save Operation
- 18. Ventilation operation 19.

13.

15.

- Numeric display
- 20. Air speed
- 21. TEST
- 22. Setting
- 23. Error
- 24. Servicing 25.
- Inspect 26.
- Timer function Numeric display 27.
- 28. Operation reservation
- 29. Days of the week
- 30. Special holiday




- 32. On/OFF button
- 33. Fan button
- 34. Mode button
- 35. Vent button
- 36. Louver button
- 37 Unit button
- 38. Save button
- 39. Swing/Fix button
- 40. Time button
- 41. Clear button

- Set button 42.
- 43. Test button
- 44. Filter reset button
- 45. Day button
- Program button 46.
- Grille button 47.
- 48. Schedule button
- 49. Temperature buttons
- 50. **ON/OFF** Light



### Group control

- Indoor units may be supplied from any phase
- Up to 8 indoor units per group, (When TCB-TC41LE remote temperature sensor is added to a "Group" the quantity of indoor units drops from 8 to 7.)
- Automatic addressing
- Any indoor unit may be designated as the "Lead Unit"
- Pre-heat indication
- Filter indication



### Automatic addressing

This takes place when power is applied and can last up to 5 minutes – the address will be selected automatically.


If a replacement indoor PCB is fitted, the missing address will be re-applied.


The powered controller screen shows the demarcation lines – and does not indicate that the system is either configuring itself – or is ready to use. If the remote temperature sensor is selected (configuration item 32), the associated symbol will appear when the system is ready for use. If a  $9^{th}$  indoor unit (which can be a protocol converter) is added to a group, the controller will continue to show the demarcation lines.

Adding a system to an existing group (or powering a group up at different times) will require manual configuration (the fault codes will provide guidance).

### Identifying an indoor unit

- Stop operation
- Press TEST (43) and VENT (35) for 4 seconds
- ALL is displayed
- Indoor fans of the entire group are now energised
- Press UNIT (37) to scroll through group
- Indoor fan of selected indoor unit runs
- Press TEST (43) to exit.





### Test operation

- System must be stopped
- Press TEST (43) for 4 seconds
- Controller displays TEST
- Press the ON/OFF (32) button to start operation
- Select MODE (34) of operation
- HEAT or COOL
- Press the ON/OFF (32) button to stop test
- System will automatically revert to normal operation after 1 hour
- Press the TEST (43) button to leave TEST function



### Controller Configuration - Remote Controller RBC-AMT32E & RBC-AMS41E

#### **Quick Reference Guide**

To assist service engineers working on Toshiba air conditioning equipment, there is a large quantity of data available via the standard remote controller, either the RBC-AMT32E or the RBC-AMS41E, this data is **NOT** available via an Infrared remote or the RBC-AS21E2 simplified remote controllers.

Accessing the data is a simple process of pressing a sequence of buttons on the remote controller.



#### Fault Code Guide

Current fault codes are displayed automatically on the left of the remote controller, (Four figure display in Black) fault code history can be accessed by pressing **"TEST & SET**" together and holding for 4 seconds. Each controller will hold four fault codes per unit controlled, the first displayed fault code is the youngest and the fourth will be the oldest. To scroll through the fault's, use the "TEMP▲▼" buttons.

Refer to the Technical Handbook for fault code diagnosis and descriptions



#### System Data

System data can be obtained by pressing **\*TEST & CL** *"* together and holding for 4 seconds. Codes are displayed on the right of the remote display. To scroll through the codes use the *"***TEMP**▲**▼***"* buttons. Data is displayed on the left of the remote controller. Data is available for "0, 1, 2, 3 & 4 Series" Digital/Super Digital inverter and VRF equipment (Mini SMMS, SHRM, SHRMi, SMMS & SMMSi).

### Controller Configuration - Remote Controller RBC-AMS51/54/55E-ES

#### **Quick Reference Guide**

To access this section on the RBC-AMS51/54/55E-ES



#### Fault Code Guide

Current fault codes are displayed automatically on the top of the remote controller, (four figure display in Black) fault code history can be accessed by entering the "field Setting Menu"

Press and hold the " [ MENU] " button and the " [ V] "button at the same time for more than 4 seconds to display the "Field setting menu" scroll down to "Alarm History". The history holds 10 fault codes per unit controlled.

Field setting	j menu
1.Test mode	
2.Register service info	6
3.Alarm history	
4.Monitor function	
5.DN setting	
Return	$\sim$
	Set

#### System Data

System data can be obtained by entering the "Field Setting Menu" and scroll down to "Monitor Function" When in monitor mode scroll through the data using the up/down buttons.



### Data Retrieval Guide - Remote Controllers RBC-AMT32E, RBC-AMS41E & RBC-AMS51/54 / 55E-ES

### Digital/Super Digital "1" Series

Code	Indoor Data	Code	Outdoor Data
00	Room Temp (Control Temp) (°C)	60	TE Sub-cooled Liquid Temp (°C)
01	Room Temp (Remote Controller) (°C)	61	TO Ambient Temp (°C)
02	TA Return Air Temp (°C)	62	TD Discharge Temp (°C)
03	TCJ Coil Liquid Temp (°C)	63	TS Suction Temp (°C)
04	TC Coil Vapour Temp (°C)	65	THS Inverter Heat Sink Temp (°C)
07	Fan Speed (rpm)	6A	Operation Current (x1 1/0) (A)
F2	Fan Run Time (x 100h)	6D	TL Liquid Temp (°C)
F3	Filter Duration Timer (x 1h)	70	Compressor Frequency (rps)
		72	Fan Speed (Lower) (rpm)
		73	Fan Speed (Upper) (rpm)
		F1	Compressor Run Time (x 100h)



### **Network Addressing DI/SDI**

#### Terminology

Terms for explaining DI/SDI used in section are redefined to:-

Indoor Unit No.	N-n =outdoor unit line address N (Max30) –indoor unit address n (max64)
Group address	0=single (not group control)
	1=Lead unit in group control
	2=sub unit in group control
Lead unit:	

The representative of multiple indoor units in group operation sends/receives signal to/from the remote controllers and sub indoor units. It has no relation with an indoor unit which communicates serially with the outdoor units. Also this unit communicates with the central controller. The operation mode and setup temperature range are reflected on the remote controller LCD. (Except air direction adjustment of louver)

#### Sub unit:

Indoor units other than master unit in group operation. Basically, sub units do not send/receive signals to/from the remote controller.

#### Header unit (Representative unit) (Master twin):


This unit communicates with the indoor unit (follower) which serial-communicates with the outdoor units and sends/receives signal (command from compressor) to/from the outdoor units as the representative of the cycle control in the outdoor units of the identical line address within the minimum unit which configures one of the refrigerating cycles of twin.

#### Follower unit (Subordinate unit) (Sub twin):

Indoor units excluding the header unit in Twin. This unit communicates with Header indoor unit in the identical line address and performs control synchronized with Header unit. This unit does not perform the signal send /receive operation with the outdoor units. No judgement for serial signal error.

#### **Basic configuration**

The basic DI/SDI connection configuration of each type of model is shown below.




#### Address re-setup for group control

After turning on the power and finishing automatic address setting, check the Indoor Unit No using the wired remote controller. If the line address is not unified in the devices in a refrigerant line, unify the line address using the wired remote controller. If group control is used, assign the group address "1" to any one of the indoor units and "2" to the rest of the units. Confirm that each indoor unit in a group has a unique Indoor Unit No (E08 error is not indicated on the wired remote controller).





#### Standard configuration (One outdoor unit)




#### In this case, address setting can be made by using auto addressing.

#### Group configuration (single only)





#### Multiple Group configuration (combination of single/twin/triple)





### Network Addressing DI/SDI

#### Connection and Address re-setup example for central control


#### "1:1Model" Connection Interface TCB-PCNT30TLE2

When controlling the super-digital inverter and the digital inverter, the adaptor named "1:1 model" connection interface (TCB-PCNT30TLE2) is necessary.


SDI series 4 4-way discharge cassette type, etc. need metal case TCB-PX30MUE additionally for fixing. Some of Hi-wall Type does not need "1:1Model" Connection Interface. Please refer to installation manual of each model.

#### Cabling connection of control wiring

Attach an adaptor per 1 group in the group control operation (including individual control). Connect the adaptor to the Master indoor unit in the group control.



A central control connection example of a system where both VRF and DI/SDI are used is shown below. The VRF and DI/SDI subsystems are connected through the central control wiring and to the central control devices.






### Network Addressing DI/SDI and VRF Systems

When the central control is performed for indoor units using twin control in a group operation, it may be required to change the group address. (Adapter is attached to the Lead indoor unit.)

**Reason:** The central control device communicates with each individual indoor unit, the Lead indoor unit of the group control and the Lead indoor unit of the twin control. However, as the address is automatically set up, which unit will become the Lead unit is indefinite. Therefore, if the unit attached with adapter does not become the Lead indoor unit, the central control function will become unavailable.



required for address change.

#### Address setup procedure (when using DI/SDI only, or using DI/SDI and VRF)

When an outdoor unit and an indoor unit are connected, or when an outdoor unit is connected to each indoor unit respectively in the group operation even if multiple refrigerant lines are provided, the automatic address setup completes with power -ON of the outdoor unit after group construction check (refer to the note below). The operation of the remote controller is not accepted while automatic address works. (Approx.4 to 5 minutes)

#### CAUTIONS

- 1. Set up address after the wiring has been completed.
- "1:1Model" Connection Interface TCB-PCNT30TLE2 is necessary for DI/SDI for central control. Some Hi-wall Type do not need "1:1Model" Connection Interface. Please refer to the installation manual of each model. Connect the central control devices to U3/U4 wires of the central control system.
- 3. When "1:1Model" Connection Interface is used for the group control or twin, triple or quad system, the interface must be connected to the Master unit of the indoor unit. (Connection to Sub unit is unavailable). One "1:1Model" Connection Interface per one group.
- 4. In group operation, be sure to turn on power supplies to all indoor units in group control within 3 minutes. When power supply of the Master unit is not turned on, there is a possibility that the Master unit exchanges with Sub unit. (If Master unit is exchanged, the central control is unavailable.)

#### Note)

If group construction is abnormal, the automatic address sequence starts automatically. Normal condition is below.

- 1. There is no duplicated indoor unit address.
- $\label{eq:2.1} \textbf{2. There is no invalid indoor unit address.}$
- 3. Individual unit and master/sub units are not intermingled.
- 4. Only a unit for Individual.
- 5. A master indoor unit and 1 or more sub indoor units for group.



### Integration with AI Network Control

TCC-net models use a different language to AI – however a TCC-net group can be linked to an AI network, by the use of a protocol converter. This device is not standard and should be fitted on site – a group requires

only one protocol converter to communicate with a network. An LED flashes to indicate communication with the network. The Protocol converter provides terminals X-Y for the network connection – it also has the 7-way DIP switch used to give a network address – the method is identical to that used for AI indoor units.

The network address may also be set by a wired controller from the configuration menu.

The protocol converter is counted as an indoor unit – only 7 indoor units may therefore be group controlled in this way.

### <u>Second Controller</u>


- ⇒ Options available
  - 2 x wired controllers
  - 1 wired + 1 infrared controller
- ⇒ Full group control from either
   ⇒ Connection may be anywhere within group
- ⇒ Connection may b
   ⇒ Changes updated

The sub-controller must be set – this can be done from either controller. The choice of sub-controller makes little difference unless it is required to act as the temperature sensor


### Temperature Sensing

Wired controllers are able to supply a temperature value to the indoor unit. This may be more representative than the standard, return air sensor but is not available from sub controllers of either type. To set the room sensor:

⇒ Wired controller – selected from configuration menu code 32, or via the "bit switch 4" on the RBC-AS41 simplified remote.



The remote sensor. This is connected to terminals A-B whether or not a wired controller is used. The indoor unit must, in this case, be set to use the standard, return air sensor – this sensor automatically takes over in this case. This value will be used to provide control to all indoor units within the group.





### Additional "Pocket Quick Reference Guides" are available covering;

Pocket Handbook of Technical Data for Toshiba R410A Range of AC Products VN-M Units, Air to Air Heat Exchangers RBC-AMT32 Standard Wired Remote Controller / AMS41E Wired Remote Controller with 7-day timer RBC-AMS51/54/55E-ES Back Light Wired Remote Controller with 7-Day Timer. R410A Mini VRF – 2-Pipe Single Vertical Fan. R410A VRF Addressing / Commissioning. R410A SMMSe Heat Pump Calculating the Refrigerant Charge. R410A SHRMe Heat Recovery Systems. FPD3 – Full AHU Control Interface. FDP3 – Modbus AHU Control Interface.

### Future Publications coming soon.

BMS-CM/SM1280ETLE Central Remote Controller. RBC-TBPTS Colour Smart touch Screen Central Remote Controller. RBC-TSI1 Universal Monitoring and Control Interface including Modbus. RBC-IS-IR-WIFI-1 Intensishome WIFI Universal Controller. RBC-TO-RC-Wifi-1 Intensishome WIFI Toshiba RAV/VRF.

You will also find Single Sheet Literature for all the current Toshiba Air Conditioning Units on our web site, along with Installation, Owners and Service manuals.

http://www.cdlweb.info

**Contact details:** 

# **Cool Designs Ltd Technical Support 07590 775510 / 07706 293028** Monday – Friday 07.30 to 19.30

Email: <u>support@cooldesignsltd.co.uk</u> Web site: <u>www.cdlweb.info</u>

> **TOSHIBA** Air Conditioning 24/7 technical support 0870 843 0333 (Option 7)

Text back service 07624 803 017 (Type fault code in lower case no spaces)





Try our on-line training videos on YouTube. Cool Designs Ltd reserves the right to change the product specifications, data and images without notice



Cool Designs Ltd makes every effort to ensure that the information provided within this publication is correct and error free, however we cannot guarantee that it is free of inaccuracies, errors or omissions. Users should seek to clarify this information for themselves prior to basing any decisions upon such information.